

Title: **M2 J5, Stockbury**

Requested output: **F- Print (Full print) Crash Report**

Date: 22-October-2019

Accident Date BETWEEN '01-Jul-2014' AND '30-Jun-2019'

There were 134 reported crashes resulting in injury

F - Print Crash Report

Date: 22-October-

Time: 10:26

M2 J5, Stockbury

Accident Date BETWEEN '01-Jul-2014' AND '30-Jun-2019'

No.1	Road A249 Section 073	Map ref: E585372 N162098	Parish: 270
			District: Maidstone
Location	A249, Stockbury Roundabout Jw M2, Sittingbourne, Kent		
Description	Veh 1 and Veh 2 Were Negotiating Rab Having both Travelled from Sittingbourne. Driver of Veh 1 Misjudged the Length of the Veh 2 and Collided with Rear Offside.		
Severity	SLIGHT	Date: 18/07/2014 Fri 21:00	DRK STL
			Road Surface Wet Weather Rain
			Speed limit 70mph
Roundabout	Roundabout No Human control within 50m		
Contributory Factors: 403V001A			
Vehicle details	Crash involved 2 vehicles		
vehicle type	location	movement	dir
registration		b-test	1st hit
1 car	mid junction	changing lane to left	NW -> SE
	did not leave c'way	negative	front
2 car	mid junction	going ahead other	NW -> SE
	did not leave c'way	negative	back
			veh hit
			2
			1
			sex
			age
			male
			77
			male
			28
Casualty details	Crash resulted in 1 casualty		
class	severity	pedestrian location	dir
		pedestrian movement	seat belt
passenger	SLIGHT		PSV passenger
in veh 1			**to/from school
			sex
			age
			female
			19

No.2	Road A249 Section 176	Map ref: E585532 N162279	Parish: 270
			District: Maidstone
Location	A249 300 Metres North of Stockbury Roundabout, Stockbury,Sittingbourne,Kent		
Description	V2 Had Stopped Behind Static Traffic Queing for Traffic Lights at Stockbury Roundabout Maidstone Bound, V1 Has Approached from Rear and Failed to Stop and Stuck V2 in the Rear.		
Severity	SLIGHT	Date: 17/08/2014 Sun 12:44	L
			Road Surface Wet Weather Rain
			Speed limit 70mph
Dual carriageway	Not at or within 20m of junction No Human control within 50m		
Contributory Factors: 103V001A 307V001A 602V001A 406V001A			

Vehicle details	Crash involved 2 vehicles		
vehicle type	location	movement	dir
registration		b-test	1st hit
			veh hit
			damaged
			sex
			age

1 car	not at junction did not leave c'way	going ahead other negative	NE -> SW front	2	male 64
2 car	not at junction did not leave c'way	waiting to go ahead but held u negative	NE -> SW back	1	male 37

Casualty details Crash resulted in 7 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						64
driver/rider	SLIGHT					male
in veh 2						37
passenger	SLIGHT					female
in veh 1						61
passenger	SLIGHT					male
in veh 1						33
passenger	SLIGHT					male
in veh 1						14
passenger	SLIGHT					male
in veh 1						12
passenger	SLIGHT					female
in veh 2						36

No.3 Road **M2** Section **064** Map ref: E585982 N162126 Parish: 31
District: Swale

Location **M2 a Junction 5 Marker Post 65/0 Sittingbourne Kent**

Description V1 Travelling on M2 a Carriageway in Lane 1 of 2 V1 Collides with Rear of V2 which was Also Travelling in Lane 1

Severity SLIGHT Date: 21/08/2014 Thu 00:40 DRK STU Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 604V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction did not leave c'way	going ahead other negative	NW -> SE front	2	female 55
2 agric veh	not at junction did not leave c'way	going ahead other negative	NW -> SE back	1	male 27

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						55
passenger	SLIGHT					female
in veh 1						19

No.4 Road **A249** Section **073** Map ref: E585359 N162006 Parish: 270
District: Maidstone

Location **A249, Stockbury Roundabout, Kent**

Description 2 Vehicle Rtc, both Vehicles Had Been Travelling in Lane One of Two Along the A249 Towards Stockbury Roundabout in the Direction of Sittingbourne. V2 Has Braked Sharply in Lane One, Causing V1 to Collide with the O/S of V2, Having Tried to Avoid.

Severity SLIGHT Date: 22/08/2014 Fri 23:07 DRK NSL Road Surface Dry Weather Rain Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 408V002A 406V001B 501V002B 404V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach did not leave c'way	going ahead other not requested	SW -> NE nearside	2	male 28
2 car	approaching or parked on approach did not leave c'way	going ahead other not requested	SW -> NE back	1	male 55

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						28
driver/rider	SLIGHT					male

No.5 Road **A249** Section **066** Map ref: E584792 N161329 Parish: 270
District: Maidstone

Location **A249, Detling Hill, South Green Lane, Maidstone, Kent**

Description V1 Appears to Have Aquaplaned on Surface Water After Heavy Rain Fall, Lost Control Careering off the Carriageway to the Nearside into Vegetation

Severity SLIGHT Date: 25/08/2014 Mon 13:00 L Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 103V001A 410V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	going ahead other	NE -> SW	0	female
	left c'way near-side	negative	front		28

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					male
in veh 1						10
passenger	SLIGHT					female
in veh 1						7

No.6 Road **A249** Section **073** Map ref: E585370 N162100 Parish: 270
District: Maidstone

Location **A249 Roundabout at Jct with M2 Exit Road, Sittingbourne**

Description V2 (Motorbike) was Crossing Roundabout in Lane 2 Heading for Sittingbourne. V1 Came from M2 Exit, Stopped for a Second then Pulled out right in Front of V2. D2 (Biker) Tried to Take Evasive Action but Hit Rear of V1 and Fell from Bike. Details Were Exchanged at the Scene but Biker Has Had to Attend Medway Hospital with Minor Injuries.

Severity SLIGHT Date: 12/09/2014 Fri 12:20 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	entering roundabout	turning right	NE -> S	2	female
	did not leave c'way	not contacted	offside		65
2 m/cycle 50 - 125cc	mid junction	going ahead other	S -> N	1	male
	did not leave c'way	not contacted	front		24

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						24

No.7 Road **A249** Section **073** Map ref: E585400 N162000 Parish: 270
District: Maidstone

Location **A249 Jw M2 Maidstone Bound, Maidstone, Kent**

Description Veh 2 was Driving Towards Maidstone. Veh 1 was in the 2Nd Lane, but Moved over Hitting Veh 2. Details Were Exchanged, but the Driver of Veh 2 Has Injuries.

Severity SLIGHT Date: 26/09/2014 Fri 15:20 L Road Surface Dry Speed limit 50mph
Weather Fine

Single carriageway Roundabout
No Human control within 50m

Contributory Factors: 405V001A 404V001A 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	mid junction	going ahead other	N -> S	2	male
	did not leave c'way	not contacted	nearside		35
2 car	mid junction	going ahead other	N -> S	1	male
	did not leave c'way	not contacted	offside		49

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					male 49

No.8 Road **A249** Section **176** Map ref: E585538 N162273 Parish: 270
District: Maidstone

Location **A249, Sittingbourne (Mapped to 585540/162270)**

Description V1 was Travelling in Lane 2 and Has Moved into Lane 1 Without Indicating Causing V2 to Brake Suddenly and V3 Has Not Had Time to Brake Sufficiently and Has Driven into the Back of V2. V1 Has Slowed down but Has Not Stopped at the Scene. V2 and V3 Did Not Get a Vrm for V1.

Severity SLIGHT Date: 11/10/2014 Sat 11:15 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 404V001A 408V002A 406V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	changing lane to left	NE -> SW	0	not known
	did not leave c'way	not contacted	did not impact		?
2 car	not at junction	going ahead other	NE -> SW	3	male
	did not leave c'way	negative	back		58
3 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	negative	front		44

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 3	SLIGHT					female 44

No.9 Road **A249** Section **073** Map ref: E585440 N162000 Parish: 270
District: Maidstone

Location **M2 Jw A249 at Stockbury, Kent**

Description V1 Requested to Stop by Police for Manner of Driving. V1 Initially Stopped and Checks Were Carried Out. it was Found That the Drivers Driving Licence is Revoked/Refused. the Driver Made off from Police and a Pursuit Started. V1 Exited the M2 Junction 5 Slip off for Stockbury. Vehicle Lost Control at the Bottom of the Slip and Collided with the Crash Barrier. There was no Contact with the Police Vehicle at this Time. There was Contact at Low Speed Prior to the Subject Vehicle Making Off.

Severity SLIGHT Date: 20/10/2014 Mon 14:02 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A 902V001A 601V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	approaching or parked on approach	going ahead left hand bend	NE -> SW	2	male
	left c'way near-side	not requested	front		25
2 car	approaching or parked on approach	going ahead left hand bend	NE -> SW	0	male
	did not leave c'way	negative	did not impact		37

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 25

No.10 Road **A249** Section **072** Map ref: E585327 N161908 Parish: 270
District: Maidstone

Location **A249, Stockbury Roundabout, Danaway, Sittingbourne**

Description Vehicles Were Slowing as They Approached Stockbury Roundabout. Vehicle One Seems to Have Shunted Vehicle Two at Such a Speed That it Has Knocked Two into Three, Three into Four and Four into Five.

Severity SLIGHT Date: 30/10/2014 Thu 10:59 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 5 vehicles

vehicle type	location	movement	dir	veh hit	sex
--------------	----------	----------	-----	---------	-----

registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach did not leave c'way	going ahead other negative	SW -> NE front	2	male 33
2 car	approaching or parked on approach did not leave c'way	waiting to go ahead but held u negative	SW -> NE back	1	male 39
3 car	approaching or parked on approach did not leave c'way	waiting to go ahead but held u negative	SW -> NE back	2	male 23
4 taxi	approaching or parked on approach did not leave c'way	waiting to go ahead but held u negative	SW -> NE back	3	male 41
5 car	approaching or parked on approach did not leave c'way	waiting to go ahead but held u negative	SW -> NE back	4	female 62

Casualty details Crash resulted in 8 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						33
driver/rider	SLIGHT					male
in veh 3						23
driver/rider	SLIGHT					female
in veh 5						62
driver/rider	SLIGHT					male
in veh 2						39
passenger	SLIGHT					female
in veh 5						21
passenger	SLIGHT					female
in veh 2						11
driver/rider	SLIGHT					male
in veh 4						41
passenger	SLIGHT					female
in veh 4						55

No.11 Road **M2** Section **063** Map ref: E584840 N162735 Parish: 197
District: Swale

Location **M2, Londonbound Hartlip, Marker Post 63/0**

Description Slow Moving Traffic, Vehicle1 Not Reacted Quickly Enough Colliding with Rear of V2 which Has then Been Pushed into V3 and V4. Minor Injury to Driver V1 Damage to All Vehicles

Severity SLIGHT Date: 26/11/2014 Wed 08:52 L Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction did not leave c'way	going ahead other not requested	SE -> NW front	2	female 19
2 car	not at junction did not leave c'way	going ahead other not requested	SE -> NW back	1	female 32
3 car	not at junction did not leave c'way	going ahead other not requested	SE -> NW back	2	female 73
4 car	not at junction did not leave c'way	going ahead other not requested	SE -> NW back	3	male 33

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						19

No.12 Road **A249** Section **177** Map ref: E585665 N162483 Parish: 31
District: Swale

Location **A249, Approx 500M West of Stockbury Roundabout, Sittingbourne, Kent (Mapped to 585660/162480)**

Description V1 Travelling Southbound on A249 Towards Stockbury Roundabout. Traffic Slowing but V1 Failed to Adjust Speed and Swerved into Lane 2 to Avoid a Collision. V1 Clipped V2 in Lane 1 Forcing V2 into V3 which Hit the Rear of V4. V1 Continued to a Stop in Lane 2.

Severity SLIGHT Date: 02/12/2014 Tue 15:30 DRK NSL Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001A 307V001B 308V001B 405V001B 406 V001B 707V001B

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
--------------	----------	----------	-----	---------	-----

registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	negative	front		29
2 car	not at junction	stopping	NE -> SW	3	female
	left c'way near-side	negative	back		58
3 car	not at junction	stopping	NE -> SW	4	male
	left c'way near-side	not provided	back		20
4 car	not at junction	waiting to go ahead but held u	NE -> SW	3	male
	did not leave c'way	negative	back		60

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						58
driver/rider	SLIGHT					male
in veh 3						20
passenger	SLIGHT					male
in veh 3						18

No.13 Road **A249** Section **177** Map ref: E585681 N162509 Parish: 31 District: Swale

Location **A249, Slip Road, M2, Sittingbourne, Kent (Mapped to 585680/162500)**

Description All 3 Vehicles Travelling in the Same Direction Towards Maidstone Approaching Stockbury Roundabout. V3 and V2 Were Stationary in Traffic when V1 Collided with the Rear of V3. Minor Injuries Sustained by Several Occupents of All 3 Vehicles.

Severity SLIGHT Date: 15/12/2014 Mon 16:17 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 308V001A 406V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	not requested	front		56
2 car	not at junction	going ahead other	NE -> SW	3	male
	did not leave c'way	negative	front		36
3 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	negative	back		41

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						56
driver/rider	SLIGHT					male
in veh 2						36
passenger	SLIGHT					male
in veh 3						5
passenger	SLIGHT					male
in veh 3						2
passenger	SLIGHT					female
in veh 2						35

No.14 Road **A249** Section **179** Map ref: E586220 N163150 Parish: 197 District: Swale

Location **A249 Danaway, Sittingbourne (Mapped to 586220,163150)**

Description Slow Moving Traffic A249 Maidstone Bound Has Come to a Stop. V2 Stopped. V1 Has Failed to Observe this and Collided with Rear of V2 Causing Minor Injuries to Person on V2.

Severity SLIGHT Date: 15/12/2014 Mon 16:20 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 408V001B 308V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	not requested	front		28
2 car	not at junction	going ahead other	NE -> SW	1	male
	did not leave c'way	not requested	back		43

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger in veh 2	SLIGHT					female 13

No.15 Road **M2** Section **065** Map ref: E586046 N162091 Parish: 31
District: Swale

Location **M2, Mp 65/0, Sittingbourne, Kent**

Description V2 Braked Heavily to Avoid Colliding with another Vehicle That Had Conducted an Emergency Stop Due to Queueing Traffic. V1 Unable to Stop in Time and Collided into the Rear of V2

Severity SLIGHT Date: 18/12/2014 Thu 17:48 DRK NSL Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 408V001A 408V002A 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	female 32
2 car	did not leave c'way	negative	front		
	not at junction	stopping	NW -> SE	1	female
	did not leave c'way	negative	back		24

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					female 32
driver/rider in veh 2	SLIGHT					female 24

No.16 Road **A249** Section **176** Map ref: E585558 N162314 Parish: 270
District: Maidstone

Location **A249 Stockbury, Sittingbourne, Kent (Mapped to 585570,162300)**

Description Vehicle Approaching Roundabout, on Braking Vehicle Skidded on Wet/Oil Road Surface Hitting Offside Barrier and Rebounding into Nearside Barrier.

Severity SLIGHT Date: 13/01/2015 Tue 14:26 L Road Surface Wet Speed limit 70mph
Weather Rain Wind

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 102V001A 103V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	0	male 62
	left c'way offside onto central res.	negative	offside		

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 62

No.17 Road **A249** Section **176** Map ref: E585608 N162389 Parish: 31
District: Swale

Location **A249, Stockbury, Sittingbourne, Kent.**

Description V2 Travelling Behind V3 Along A249 Towards Stockbury Roundabout. V1 Tried to Pull into a Gap Too Small to Fit Causing V2 to Brake and Swerve, Clipping the Rear Offside Bumper of V3. this Has Caused V2 to Swerve from Lane 2 across Carriageway onto Verge Hitting Tree Head On. V1 Has Swerved Spun Around Slid the Nearside of Car Along the Armco Barrier in Central Reservation, Swerved across the Carriageway, onto the Verge, Damaging the Rear of the Vehicle on Trees/Bushes.

Severity SLIGHT Date: 28/01/2015 Wed 06:55 DRK NSL Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 403V001B 405V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	changing lane to right	NE -> SW	2	male

2 car	left c'way Offside not at junction	not contacted going ahead other	nearside NE -> SW	3	39 female
3 car	left c'way Offside not at junction	not contacted going ahead other	front NE -> SW	2	22 male
	did not leave c'way	not contacted	back		20

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						39
driver/rider	SLIGHT					female
in veh 2						22

No.18 Road **A249** Section **176** Map ref: E585520 N162241 Parish: 270
District: Maidstone

Location **A249, 275 Metres North East of Stockbury Roundabout, Sittingbourne, Kent**

Description V1 was Driving Towards Stockbury Roundabout. as D1 Took Their Eyes off the Road Briefly, when They Looked Back at the Road They Saw the Traffic Had Stopped. D1 Tried to Brake but Collided with the Rear of V2. this then was Shunted into V3 which in Turn Hit V4.

Severity SLIGHT Date: 20/02/2015 Fri 09:40 L Road Surface Wet Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 308V002B 308V003B

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	not requested	front		34
2 car	not at junction	stopping	NE -> SW	1	male
	did not leave c'way	not requested	back		61
3 car	not at junction	stopping	NE -> SW	2	female
	did not leave c'way	not requested	back		35
4 car	not at junction	stopping	NE -> SW	3	female
	did not leave c'way	not requested	back		29

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						61
passenger	SLIGHT					female
in veh 3						8
passenger	SLIGHT					female
in veh 3						6

No.19 Road **M2** Section **064** Map ref: E585714 N162256 Parish: 31
District: Swale

Location **M2 B Mp 64/7, Stockbury, Kent**

Description Single Vehicle Rtc. V1 Had Been Travelling from the Slip Road at Jct 5 Stockbury Roundabout, when Various Warning Lights Illuminted on Their Dashboard and the Vehicle Seized. this Caused D1 to Lose Control and Collide with Central Barrier. no Witness or Other Vehicles Involved. Damage to Central Reservation.

Severity SLIGHT Date: 08/03/2015 Sun 13:00 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001B 410V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	starting	SE -> NW	0	female
	left c'way offside onto central res.	negative	offside		24

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						24

No.20 Road **M2** Section **063** Map ref: E584583 N162886 Parish: 197
District: Swale

Location **M2 London Bound Between Junctions 5-4 at Marker Post 63/4, Hartlip, Kent.**

Description 2 Vehicle Rtc V1 Has Collided into Rear of V2 Knocking the Rider from Their Machine.

Severity SERIOUS Date: 10/03/2015 Tue 20:23 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001B 406V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	not at junction	going ahead other	SE -> NW	2	male
	did not leave c'way	negative	front		51
2 m/cycle 125 - 500cc	not at junction	going ahead other	SE -> NW	1	male
	did not leave c'way	not requested	back		52

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						51
driver/rider	SERIOUS					male
in veh 2						52

No.21 Road **A249** Section **066** Map ref: E584798 N161330 Parish: 270
District: Maidstone

Location **A249, Sittingbourne Road Jw South Green Lane, Maidstone, Kent**

Description V1 Seen by Witnesses to Hit Standing Water and Lose Control, Spun and Hit Central Barrier. Vehicle Reported Travelling at Normal Speed.

Severity SERIOUS Date: 29/03/2015 Sun 17:29 L Road Surface Wet Weather Rain Speed limit 70mph

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 101V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	going ahead other	NE -> SW	0	male
	left c'way offside onto central res.	negative	offside		41

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						41

No.22 Road **A249** Section **073** Map ref: E585450 N162054 Parish: 270
District: Maidstone

Location **A249 Stockbury Roundabout Jw M2, Stockbury, Sittingbourne, Kent**

Description V2 Travelling on Major Carriageway (A249 Sittingbourne), Negotiated Roundabout in Outside Lane Intending to Join Motorway (M2 London). V1 Travelling on Major Carriageway (A249) from Sittingbourne Negotiated Roundabout in Inside Lane Intending to Join Dual Carriageway (A249 Maidstone). as V2 Held Position for Roundabout (Outside Lane) V1 Attempted to Pass in Front of V2 and Leave Roundabout Using Lane 2 of A249. V1 Had Insufficient Room for Manoeuvre and Collision Occurred.

Severity SLIGHT Date: 06/05/2015 Wed 15:05 L Road Surface Dry Weather Fine Speed limit 70mph

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	going ahead other	NE -> SW	2	male
	did not leave c'way	not requested	offside		54
2 goods > 7.5t	mid junction	going ahead other	NE -> E	1	male
	did not leave c'way	negative	nearside		27

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					female

No.23 Road **F1911** Section **191** Map ref: E586318 N163185 Parish: 31
District: Swale

Location **Maidstone Road Jw Oak Close, Chestnut Street**

Description V2 Driving from Key Street to Stockbury. V1 Pulled out of Oak Close turning right Towards Key Street. V1 Vision Obscured by Parked Vehs, Continued to Pull out of Junction into Path of V2 Causing Collision.

Severity SLIGHT Date: 22/05/2015 Fri 08:27 L Road Surface Dry Weather Fine Speed limit 50mph

Single carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 406V001A 701V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	entering main road	turning right	SE -> NE	2	female
	did not leave c'way	negative	front		37
2 car	approaching or parked on approach	going ahead other	NE -> SW	1	male
	left c'way Offside	negative	nearside		32

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					female
in veh 2						44

No.24 Road **M2** Section **064** Map ref: E585194 N162559 Parish: 197
District: Swale

Location **M2 'A' Carriageway Marker Post 64/1, Stockbury, Kent**

Description V1 to V5 Travelling South East Along the M2 in Lane Two of a Possible 2 Lanes. Congestion on the Approach to Jct 5 Causing a Build up of Traffic Causing Vehicles to Slow/Stop. as a Result of the Slowing Traffic, V1 Collided into the Rear of V2. V4 Travelling Directly Behind V1 Came to a Satisfactory Stop but was Subsequently Collided into by V3 Pushing it into the Rear of V1. V5 then Collided into the Rear of V3. (No Further Casualty Details Known by Police, Other Than What is Already Recorded)

Severity SLIGHT Date: 24/05/2015 Sun 11:51 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001A 308V003A 308V005A

Vehicle details Crash involved 5 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NW -> SE	2	male
	did not leave c'way	negative	front		50
2 car	not at junction	stopping	NW -> SE	1	male
	did not leave c'way	negative	back		29
3 car	not at junction	stopping	NW -> SE	4	male
	did not leave c'way	negative	front		62
4 car	not at junction	stopping	NW -> SE	3	male
	did not leave c'way	negative	back		58
5 car	not at junction	stopping	NW -> SE	3	female
	did not leave c'way	negative	front		57

Casualty details Crash resulted in 8 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						50
driver/rider	SLIGHT					male
in veh 3						62
driver/rider	SLIGHT					female
in veh 5						57
passenger	SLIGHT					female
in veh 3						60
passenger	SLIGHT					male
in veh 5						59
passenger	SLIGHT					male
in veh 1						?
passenger	SLIGHT					female
in veh 1						?
passenger	SLIGHT					female
in veh 1						?

No.25 Road **M2** Section **064** Map ref: E585196 N162559 Parish: 197
District: Swale

Location **M2 'A' Carriageway Near to Marker Post 64/1**

Description V3 Had Been Involved in Slight Damage Rtc Due to Traffic (Fender/Bender) on M2 'A' Carriageway. V2 Stopped Behind These Vehs but was Hit at Speed by V1. this Caused a 2Nd Rtc with Force - a Collision Pushing All Vehs Together. V1 Hitting V2, V2 Hitting V3, V3 Hitting V4. Whiplash Injury Sustained by Driver of V3. Driver of V2 Also Sustaining Injury.

Severity SLIGHT Date: 25/05/2015 Mon 11:52 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001B 408V002B 308V001A

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	male
	did not leave c'way	negative	front		55
2 car	not at junction	stopping	NW -> SE	1	male
	did not leave c'way	negative	back		33
3 car	not at junction	stopping	NW -> SE	2	female
	did not leave c'way	negative	back		22
4 car	not at junction	parked	NW -> P	3	female
	did not leave c'way	not requested	back		21

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 3						22
driver/rider	SLIGHT					female
in veh 4						21

No.26 Road **M2** Section **063** Map ref: E584757 N162786 Parish: 197
District: Swale

Location **M2, Marker Post 63/6, London Bound Carriageway, Stockbury, Kent**

Description both Vehicles Travelling London Bound on M2 at Stockbury. V1 Has Hit V2 from Behind and left Scene.

Severity SLIGHT Date: 22/06/2015 Mon 23:52 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 501V001B 502V001B 601V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	2	not known
	did not leave c'way	not contacted	front		?
2 goods < 3.5t	not at junction	going ahead other	SE -> NW	1	male
	did not leave c'way	negative	back		21

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						21

No.27 Road **M2** Section **065** Map ref: E586406 N161891 Parish: 31
District: Swale

Location **M2 Mp 65/5 A, Borden, Kent**

Description Heavy Traffic on the M2 Caused Traffic to Slow to a Stop/Start Situation. V2 and V1 Were both in Lane 2 of 2, V2 Braked Heavily for a Lorry in Front. V1 Didnt Brake Heavily Enough and Collided with the Rear of V2.

Severity SLIGHT Date: 04/07/2015 Sat 10:45 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001A 406V001A 408V002A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NW -> SE	2	male
	did not leave c'way	negative	front		38
2 car	not at junction	stopping	NW -> SE	1	male

Location **A249 Detling Hill J/W Honeycrook Hill, Maidstone**

Description V1 Has Turned right from the A249 onto Honeycrook Hill and Has Collided with Cyclist Throwing Them up into the Air and onto Windscreen.

Severity SERIOUS Date: 19/07/2015 Sun 18:55 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	leaving main road	turning right	NE -> W	2	female
	did not leave c'way	negative	nearside		80
2 pedal cycle	approaching or parked on approach	going ahead other	SW -> NE	1	male
	did not leave c'way	not requested	front		32

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school	age	
driver/rider	SERIOUS					male
in veh 2						32

No.31 Road **A249** Section **176** Map ref: E585590 N162361 Parish: 31
District: Swale

Location **A249, Mp 64/5, Sittingbourne, Kent**

Description V1 (Lorry) Has Approached Stationary Traffic on Dual Carriageway. V1 Has Not Slowed/Stopped in Time and Has Hit V2 from Behind Shunting it into V3 and V4. V1 Has then Reversed off V2 Hitting V5 to Front.

Severity SLIGHT Date: 21/07/2015 Tue 16:35 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001B 406V001B 510V001B 706V001B

Vehicle details Crash involved 5 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	negative	front		41
2 car	not at junction	stopping	NE -> SW	1	male
	did not leave c'way	not requested	back		53
3 car	not at junction	waiting to go ahead but held u	NE -> SW	2	female
	did not leave c'way	not requested	back		66
4 car	not at junction	waiting to go ahead but held u	NE -> SW	3	male
	did not leave c'way	not requested	back		35
5 car	not at junction	stopping	NE -> NW	2	male
	did not leave c'way	not requested	front		17

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school	age	
driver/rider	SLIGHT					male
in veh 2						53
driver/rider	SLIGHT					female
in veh 3						66
driver/rider	SLIGHT					male
in veh 4						35
driver/rider	SLIGHT					male
in veh 5						17
passenger	SLIGHT					male
in veh 5						18

No.32 Road **M2** Section **064** Map ref: E585473 N162406 Parish: 31
District: Swale

Location **M2, a Slip on Coast Bound, Sittingbourne, Kent**

Description V1 Joining M2 a C/Way from A249 in Lane 2 OF 2 on Main Carriageway. V1 Pulls into L2 to Overtake Slow Moving Lorries and Vehicle Collided. Medical Episode.

Severity SERIOUS Date: 27/07/2015 Mon 20:41 DRK STL Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Slip Road
No Human control within 50m

Contributory Factors: 306V002A 405V001B 406V001B 602V002B 505 V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	entering from slip road	changing lane to right	N -> S	2	male
	did not leave c'way	negative	back		51
2 car	approaching or parked on approach	going ahead other	N -> S	1	male
	did not leave c'way	negative	front		34

Casualty details Crash resulted in 4 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						51
passenger	SLIGHT					male
in veh 1						79
passenger	SLIGHT					female
in veh 2						68
passenger	SLIGHT					male
in veh 2						49

No.33 Road **A249** Section **069** Map ref: E585083 N161674 Parish: 270
District: Maidstone

Location **A249 Stockbury Jw Honeycrock Hill, Sittingbourne, Kent**

Description Traffic was Heavy but Moving in both of the Two Lanes of the A249 Approaching Stockbury R/A in the Direction of Sittingbourne. V2 Travelling in L2. V3 Manoeuvred from L1 to L2 ahead of V2 Causing V2 to Brake and Reduce Speed. V1 was Unable to React in Time and Collided with the Rear of V2 in L2.

Severity SLIGHT Date: 03/08/2015 Mon 18:15 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	approaching or parked on approach	going ahead other	SW -> NE	2	male
	did not leave c'way	negative	front		21
2 car	approaching or parked on approach	stopping	SW -> NE	1	male
	did not leave c'way	not requested	back		29
3 goods < 3.5t	approaching or parked on approach	changing lane to right	SW -> NE	0	not known
	did not leave c'way	not requested	did not impact		?

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						29
passenger	SLIGHT					male
in veh 2						15
passenger	SLIGHT					male
in veh 2						6
passenger	SLIGHT					female
in veh 2						41
passenger	SLIGHT					male
in veh 2						12

No.34 Road **M2** Section **064** Map ref: E585135 N162595 Parish: 197
District: Swale

Location **M2 Stockbury, Sittingbourne, Kent (Mapped to 585130/162590)**

Description V1 Travelling Towards Junction 5 of the M2 Has Changed from Lane 1 to Lane 2, and Failed to Observe Vehicles Slowing and Stopped Due to Heavy Traffic and Collided with Rear of V2, in Turn, Pushing it into V3, V4, V5, V6. Minor Injuries to Occupants of Other Vehicles.

Severity SLIGHT Date: 08/08/2015 Sat 11:31 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Slip Road
No Human control within 50m

Contributory Factors: 406V001A 408V001B

Vehicle details Crash involved 6 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	stopping	NW -> SE	2	male
	did not leave c'way	negative	front		34
2 car	mid junction	stopping	NW -> SE	3	male
	did not leave c'way	negative	back		68

3 car	mid junction did not leave c'way	stopping negative	NW -> SE back	4	female 34
4 car	mid junction did not leave c'way	stopping negative	NW -> SE back	5	female 21
5 car	mid junction did not leave c'way	stopping negative	NW -> SE back	6	female 42
6 car	mid junction did not leave c'way	stopping negative	NW -> SE back	0	female 29

Casualty details Crash resulted in 9 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					male 68
driver/rider in veh 3	SLIGHT					female 34
driver/rider in veh 6	SLIGHT					female 29
passenger in veh 2	SLIGHT					female 68
passenger in veh 3	SLIGHT					female 94
passenger in veh 3	SLIGHT					male 37
passenger in veh 3	SLIGHT					female 4
passenger in veh 1	SLIGHT					female 0
passenger in veh 1	SLIGHT					female 20

No.35 Road **M2** Section **065** Map ref: E586155 N162034 Parish: 31
District: Swale

Location **M2, Marker Post 65/2, a Carriageway, Stockbury, Kent**

Description V3 was Travelling in Lane 2, North Bound Towards Faversham in Heavy Traffic, Followed by V2 which was Followed by V1. V3 Slowed to a Stop Due to Volume of Traffic, as Did V2. V1 Failed to Notice the Stationary Traffic and Collided with the Rear of V2, which Collided With the Rear of V3.

Severity SLIGHT Date: 15/08/2015 Sat 12:25 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001A 405V001A

Vehicle details Crash involved 3 vehicles

vehicle type registration	location	movement b-test	dir 1st hit	veh hit damaged	sex age
1 car	not at junction did not leave c'way	stopping negative	NW -> SE front	2	female 52
2 car	not at junction did not leave c'way	stopping negative	NW -> SE back	1	female 22
3 car	not at junction did not leave c'way	stopping negative	NW -> SE back	2	female 42

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger in veh 2	SLIGHT					female 7

No.36 Road **A249** Section **073** Map ref: E585359 N162011 Parish: 270
District: Maidstone

Location **A249 Stockbury Roundabout, Sittingbourne, Kent**

Description V1 Has Driven into the Rear of V2 Waiting at a Junction to the Roundabout

Severity SLIGHT Date: 29/09/2015 Tue 17:10 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type registration	location	movement b-test	dir 1st hit	veh hit damaged	sex age
1 goods 3.5 - 7.5t	approaching or parked on approach did not leave c'way	going ahead other negative	SW -> NE front	2	male 25

2 car approaching or parked on approach waiting to go ahead but held u SW -> NE 1 female
 did not leave c'way negative back 31

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					female 31

No.37 Road **A249** Section **073** Map ref: E585438 N162101 Parish: 270
 District: Maidstone

Location **A249 Stockbury Roundabout, Maidstone Bound, Sittingbourne, Kent**

Description V2 Sat in Traffic, V1 Struck V2 from the Rear Causing Damage and Injuries. V2 Indicated for V1 to Pull over at a Safe Place. V1 Ignored this and Drove off Towards M2.

Severity SLIGHT Date: 05/10/2015 Mon 18:15 L Road Surface Dry Speed limit 70mph
 Weather Unknown

Dual carriageway Roundabout
 No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	approaching or parked on approach did not leave c'way	going ahead other not contacted	NE -> SW front	2	not known ?
2 car	approaching or parked on approach did not leave c'way	going ahead other not contacted	NE -> SW back	1	female 37

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					female 37

No.38 Road **A249** Section **177** Map ref: E585798 N162688 Parish: 197
 District: Swale

Location **A249, Sittingbourne, Kent (Mapped to 585800, 162680)**

Description V1, V2 Travelling South Along A249. V2 Slowed Due to Traffic, V1 Went into Rear of V2. Driver of V1 Said They Had Sneezed Causing Collision. S170 Complied With. (D1 Age Not Known)

Severity SLIGHT Date: 14/10/2015 Wed 15:40 L Road Surface Dry Speed limit 70mph
 Weather Fine

Dual carriageway Not at or within 20m of junction
 No Human control within 50m

Contributory Factors: 406V001B 509V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction left c'way offside onto central res.	going ahead other not contacted	NE -> SW front	2	male ?
2 car	not at junction did not leave c'way	stopping not contacted	NE -> SW back	1	female 50

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					female 50

No.39 Road **A249** Section **176** Map ref: E585559 N162305 Parish: 270
 District: Maidstone

Location **A249 200 Metres North of Stockbury Roundabout, Stockbury, Kent**

Description Stopped Traffic Queuing for Roundabout, V1 Goes into Rear of V2.

Severity SLIGHT Date: 23/10/2015 Fri 12:37 L Road Surface Dry Speed limit 70mph
 Weather Fine

Dual carriageway Not at or within 20m of junction
 No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
--------------	----------	----------	-----	---------	-----

registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	negative	front		63
2 goods < 3.5t	not at junction	going ahead other	NE -> SW	1	male
	did not leave c'way	negative	back		47

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						63

No.40 Road **A249** Section **176** Map ref: E585589 N162356 Parish: 31 District: Swale

Location **A249, Southbound, 300 Yards Prior to Stockbury Roundabout, Sittingbourne, Kent**

Description V1 was Travelling Behind V2 on the Southbound Carriageway of the A249, at the 300 Yard Marker Prior to Stockbury Roundabout. V1 Failed to Slow down or Stop. it was at That Point V1 Drove into the Back of V2.

Severity SLIGHT Date: 22/11/2015 Sun 16:06 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 705V001B 406V001B 503V001B 405V001B 308 V001B 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	negative	front		42
2 car	not at junction	going ahead other	NE -> SW	1	male
	did not leave c'way	not requested	back		23

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						42

No.41 Road **M2** Section **064** Map ref: E585192 N162545 Parish: 197 District: Swale

Location **M2 Mp 64/1, Sittingbourne, Kent**

Description V2 Stopped as Traffic ahead Had Stopped. V1 Hit Rear of V2. V4 then Stopped and was Hit in Rear by V3. All Traffic was Travelling at Reduced Speed Due to Heavy Congested Traffic.

Severity SLIGHT Date: 08/12/2015 Tue 08:35 DRK STL Road Surface Wet Weather Rain Speed limit 70mph

Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 308V001A 308V003A 406V001A

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	2	female
	did not leave c'way	negative	front		45
2 car	not at junction	going ahead other	SE -> NW	1	male
	did not leave c'way	negative	back		38
3 car	not at junction	going ahead other	SE -> NW	4	male
	did not leave c'way	negative	front		38
4 car	not at junction	going ahead other	SE -> NW	3	male
	did not leave c'way	negative	back		23

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 4						23

No.42 Road **A249** Section **176** Map ref: E585591 N162359 Parish: 31 District: Swale

Location **A249, Sittingbourne, Kent (Mapped to 585600,162340)**

Description V2 Driving on a Dual Carriageway in Lane 1 , Came to a Stop Due to Traffic. V2 Behind V3, Slowed down Almost to a Stop. V1 Didn't Slow down Much and Hit Rear End of V2, Pushing V2 into 3.

Severity SLIGHT Date: 20/12/2015 Sun 10:40 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 602V001B 308V001A 408V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	negative	front		73
2 car	not at junction	stopping	NE -> SW	1	female
	did not leave c'way	negative	back		27
3 car	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	negative	back		33

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						73
driver/rider	SLIGHT					female
in veh 2						27
passenger	SLIGHT					male
in veh 2						31

No.43 Road **A249** Section **179** Map ref: E586175 N163106 Parish: 197
District: Swale

Location **A249, Approach to Stockbury Roundabout, Near M2 Bridge, Sittingbourne, Kent (Mapped to 586170/163100)**

Description V1 Has Signalled to Change Lanes (From 1-2) to Pass a Broken down Vehicle, V1 Has Failed to Move over in Time Due to Traffic in Lane 2 and Has Also Failed to Slow or Stop in Time Colliding with V2 which Collided with V3, which Collided with V4, which Collided with V5.

Severity SERIOUS Date: 22/12/2015 Tue 12:42 L Road Surface Wet Speed limit 70mph
Weather Rain Wind

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001B 307V001B 405V001B 406V001B 408 V001B

Vehicle details Crash involved 5 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	changing lane to right	NE -> SW	2	male
	did not leave c'way	negative	front		53
2 car	not at junction	waiting to go ahead but held u	NE -> SW	1	female
	did not leave c'way	negative	back		30
3 goods < 3.5t	not at junction	waiting to go ahead but held u	NE -> SW	2	male
	did not leave c'way	not requested	back		26
4 goods < 3.5t	not at junction	waiting to go ahead but held u	NE -> SW	3	male
	left c'way near-side	negative	back		24
5 car	not at junction	waiting to go ahead but held u	NE -> SW	4	female
	did not leave c'way	negative	back		69

Casualty details Crash resulted in 4 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					female
in veh 2						30
driver/rider	SLIGHT					male
in veh 3						26
driver/rider	SLIGHT					male
in veh 4						24
driver/rider	SLIGHT					female
in veh 5						69

No.44 Road **A249** Section **066** Map ref: E584799 N161329 Parish: 277
District: Maidstone

Location **A249 JW SOUTH GREEN LANE, STOCKBURY**

Description V1 travelling maidstone bound from Stockbury roundabout A249, V1 in lane 2 of two lane carriageway following another car travelling at high speed and too close. V1 then lost control for unknown reason clipping offside verge and mounts central reservation , V1 travels along central barrier for some distance before flipping over several times across carriageway, coming to a rest on its roof on nearside verge (SEATBELT DETAILS NOT PROVIDED)

Severity SLIGHT Date: 16/01/2016 Sat 11:13 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 410V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	N -> S	0	male
	left c'way offside onto central res.	negative	offside		25

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						25

No.45 Road **A249** Section **176** Map ref: E585535 N162263 Parish: 270
District: Maidstone

Location **A249, 65/0, Junction 300 Metres North M2 J5 Roundabout, Sittingbourne, Kent**

Description V1 Approached Queue of Traffic at Stockbury Roundabout Approaching on A249 . V1 Struck V2. Momentum of V1 Pushed V2 Forward. V1 Continued with Momentum Away from Lane 1 across Lane 2 and Bounced off Central Reservation Back across Lane 2 and Struck Rear of V3 which Spun out into Lane 2. V1 Continued across Lane 1 and Stopped, Impacted with Nearside Armco.

Severity SERIOUS Date: 16/01/2016 Sat 12:53 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 709V001B 706V001B 510V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	left c'way offside and rebounded	not contacted	front		51
2 car	not at junction	waiting to go ahead but held u	NE -> SW	1	male
	did not leave c'way	not contacted	back		68
3 car	not at junction	waiting to go ahead but held u	NE -> SW	1	female
	did not leave c'way	not contacted	back		36

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						51
passenger	SERIOUS					male
in veh 1						6

No.46 Road **A249** Section **063** Map ref: E584524 N161119 Parish: 270
District: Maidstone

Location **A249, 100M SOUTH OF JW CHURCH HILL, STOCKBURY**

Description 1 X VEHICLE RTC. D1 BELIEVES V1 HAS SUFFERED SOME FORM OF MECHANICAL FAILURE WHICH CAUSED RIDER TO LOSE CONTROL.

Severity SLIGHT Date: 26/01/2016 Tue 13:10 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 204V001B 410V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SW -> NE	0	male
	left c'way near-side	negative	nearside		30

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						30

No.47 Road **A249** Section **0** Map ref: E585341 N162001 Parish: 270
District: Maidstone

Location **A249 MAIDSTONE BOUND PRIOR TO JW HONEYCROCK HILL, MAIDSTONE**

Description An HGV has manoeuvred into the right hand feeder lane towards Stockbury. Due to the length of the vehicle this has left part of the vehicle sticking out into L2 of the A249. Other vehicles have had to slow suddenly and V1 has collided with the rear of V2 due to wet road conditions in the area.

Severity SLIGHT Date: 03/03/2016 Thu 05:30 DRK NSL Road Surface Wet Speed limit 70mph
Weather Rain Wind

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	negative	front		53
2 car	not at junction	waiting to go ahead but held u	NE -> SW	1	male
	did not leave c'way	negative	back		41

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						53

No.48 Road **M2** Section Map ref: E585555 N162499 Parish: 31
District: Swale

Location **M2 OFF SLIP, J5 COASTBOUND JW A249 DETLING HILL, STOCKBURY (MAPPED TO 58555,162499)**

Description SINGLE VEH RTC. V1 DRIVING ON SLIP ROAD OFF M2 J5 COASTBOUND FAILED TO NEGOTIATE BEND IN ROAD COLLIDING WITH ROADSIDE FURNITURE. WHIPLASH INJURY TO DRIVER AND SINGLE PAX. S170 COMPLIED.

Severity SLIGHT Date: 06/03/2016 Sun 17:48 L Road Surface Wet Speed limit 70mph
Weather Fine

Slip road Slip Road
No Human control within 50m

Contributory Factors: 403V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead right hand bend	W -> SW	0	female
	left c'way near-side	not requested	front		21

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						21
passenger	SLIGHT					male
in veh 1						24

No.49 Road **A249** Section **177** Map ref: E585655 N162519 Parish: 31
District: Swale

Location **A249, SITTINGBOURNE**

Description V1 collided with V2 who was stopped on A249 carriageway, due to a distraction in vehicle.

Severity SLIGHT Date: 17/03/2016 Thu 20:48 DRK NSL Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 409V001B 509V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	negative	front		21
2 goods > 7.5t	not at junction	waiting to go ahead but held u	NE -> SW	1	male
	did not leave c'way	negative	back		63

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						21

No.50 Road **A249** Section **176** Map ref: E585501 N162263 Parish: 270
District: Maidstone

Location **A249 MAIDSTONE ROAD, MAPPED TO (585501,162263)**

Description V1 HAS LEFT THE ROUNDABOUT AT A249, STOCKBURY HEADING TOWARDS THE ISLE OF SHEPPEY ON THE A249, APPROXIMATELY 50M ALONG THE A249 THE VEHICLE BECAME UNSTEERABLE AND CRASHED INTO THE VERGE ON THE N/S.

D1 THEN MOVED THEIR VEHICLE ONTO THE LAYBY TO AWAIT THE POLICE.

Severity SLIGHT Date: 06/04/2016 Wed 03:00 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 106V001B 108V001B 410V001A 503V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SW -> NE	0	male
	left c'way near-side	negative	front		33

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						33
passenger	SLIGHT					male
in veh 1						39

No.51 Road **A249** Section **066** Map ref: E584776 N161330 Parish: 270
District: Maidstone

Location **A249, 100M SOUTH OF JW AMELS HILL, STOCKBURY**

Description V1 travelling northbound on A249 at Stockbury following V2. V2 slowed due to traffic congestion ahead and braked. V1 collided with rear of V2. Driver of V1 is a provisional licence holder (driving unaccompanied and no 'L' plates)

Severity SLIGHT Date: 19/04/2016 Tue 18:30 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SW -> NE	2	male
	did not leave c'way	negative	front		36
2 car	not at junction	going ahead other	SW -> NE	1	female
	did not leave c'way	negative	back		47

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						47
passenger	SLIGHT					female
in veh 2						26

No.52 Road **M2** Section **065** Map ref: E586123 N162054 Parish: 131
District: Swale

Location **M2, SITTINGBOURNE (MAPPED TO 586129,162054)**

Description V1 HAS COLLIDED WITH REAR OF V2 IN TRAFFIC.

Severity SLIGHT Date: 07/05/2016 Sat 10:40 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors:

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	female
	did not leave c'way	negative	front		20
2 car	not at junction	going ahead other	NW -> SE	1	male
	did not leave c'way	negative	back		24

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						20

No.53 Road **A249** Section Map ref: E584981 N161598 Parish: 270
District: Maidstone

Location **A249 300 METRES SOUTH OF JW M2, SITTINGBOURNE**

Description V1 BEHIND V2 IN TRAFFIC APPROACHING R/A. V2 SLOWED TO A HALT AND V1 FAILED TO REACT IN TIME COLLIDING WITH THE REAR OF V2. (MAPPED TO 584981,161598)

Severity SLIGHT Date: 08/05/2016 Sun 16:22 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SW -> NE	2	female
	did not leave c'way	negative	front		54
2 car	not at junction	waiting to go ahead but held u	SW -> NE	1	female
	did not leave c'way	negative	back		23

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						54
driver/rider	SLIGHT					female
in veh 2						23

No.54 Road **A249** Section **073** Map ref: E585439 N162076 Parish: 270
District: Maidstone

Location **A249, STOCKBURY ROUNDABOUT, 5M SOUTH OF JW CHESTNUT STREET, STOCKBURY**

Description V2 WAS DRIVING FROM A249 ACROSS THE R/A COMING OFF AT THE LONDON EXIT ON THE R/A. AS V2 WENT PAST JW CHESTNUT STREET V1 (M/C) PULLED OUT OF THE JUNCTION IN FRONT OF V2. V1 LOST CONTROL WHILST TRYING TO AVOID HITTING THE V2. D1 WAS COMPLAINING OF WRIST PAIN. SECAS ATTENDED TO CHECK THE RIDER. NO DAMAGE TO EITHER VEHICLE. S172 COMPLIED

Severity SERIOUS Date: 26/05/2016 Thu 17:27 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 406V001B 308V001B 405V001B 408V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 m/cycle 125 - 500cc	entering roundabout	going ahead other	NE -> SW	0	male
	did not leave c'way	not requested	front		57
2 car	mid junction	going ahead other	N -> SW	0	female
	did not leave c'way	not requested	did not impact		30

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						57

No.55 Road **M2** Section **064** Map ref: E585813 N162099 Parish: 31
District: Swale

Location **M2, MP 64/9, B SLIP OFF, JUNCTION 5, STOCKBURY**

Description V1 LOST CONTROL ON SLIP ROAD BEND AND LEFT THE CARRIAGEWAY ON NEAR SIDE INTO THE BUSHES

Severity SLIGHT Date: 31/05/2016 Tue 11:44 L Road Surface Wet Speed limit 70mph
Weather Rain Wind

Slip road Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	0	male
	left c'way near-side	not contacted	front		46

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 46

No.56 Road **A249** Section **073** Map ref: E585356 N162085 Parish: 270
District: Maidstone

Location **A249 JW M2, STOCKBURY**

Description V1 hit back of v2 at roundabout

Severity SLIGHT Date: 28/06/2016 Tue 12:47 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	SW -> NE	2	male
	did not leave c'way	negative	front		38
2 car	leaving roundabout	waiting to go ahead but held u	SW -> NE	1	female
	did not leave c'way	negative	back		45

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					female 45

No.57 Road **M2** Section **063** Map ref: E584538 N162931 Parish: 197
District: Swale

Location **M2, MP 63/2 500 METRES WEST OF JUNCTION WITH MAIDSTONE ROAD A249**

Description Slow moving traffic, stop start from medway services area. Vs 2&3 stopped. V1 skidded, collided with v2 pushing it into the central barrier. V1 also collided with v3

Severity SLIGHT Date: 15/07/2016 Fri 13:40 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 406V001A 408V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 goods > 7.5t	not at junction	stopping	E -> W	0	male
	did not leave c'way	negative	front		47
2 car	not at junction	stopping	E -> W	0	male
	did not leave c'way	negative	back		59
3 car	not at junction	stopping	E -> W	0	male
	did not leave c'way	not contacted	back		53

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 2	SLIGHT					male 59

No.58 Road **A249** Section Map ref: E585374 N162097 Parish: 270
District: Maidstone

Location **A249, STOCKBURY ROUNDABOUT J/W M2 JUNCTION 5**

Description V1 turning right on the roundabout however from the incorrect left hand lane turning across the path of V2 who was passing on V1's off side in the correct lane to travel straight ahead or right at the roundabout. Both vehicles entered the roundabout from the A249 Maidstone bound carriageway.

Severity SLIGHT Date: 26/07/2016 Tue 11:45 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A 405V001A 602V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age

1 goods 3.5 - 7.5t	mid junction	turning right	S -> E	0	male
	did not leave c'way	negative	front		53
2 car	mid junction	o/t moving vehicle on its O/S	S -> N	0	male
	did not leave c'way	negative	back		23

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					male
in veh 2						1

No.59 Road **M2** Section **063** Map ref: E584642 N162871 Parish: 197
District: Maidstone

Location **M2, JUNCTIONS 3-5 (MAPPED TO 584616,162831)**

Description V1 is a motorbike which drove into the rear of a camper van on M2 Coastbound between junction 3-5 when it braked suddenly. Both vehicles stopped and V1 gave details to V2 but did not take theirs so unknown V2 details. V1 continued en route to their location when his pillion passenger started complaining of back injury/pain. They pulled over at Newington and called ambulance.

Severity SLIGHT Date: 29/08/2016 Mon 12:00 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 408V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 m/cycle > 500cc	not at junction	going ahead other	NW -> SE	0	male
	did not leave c'way	negative	front		60
2 car	not at junction	going ahead other	NW -> SE	0	not known
	did not leave c'way	not contacted	back		?

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					female
in veh 1						24

No.60 Road **A249** Section **179** Map ref: E586178 N163101 Parish: 197
District: Swale

Location **A249, MAIDSTONE ROAD**

Description V1 was travelling southbound on the A249 approaching the traffic lights at Stockbury roundabout. V1 was not paying attention to the slowing traffic in front of them and hit V2 who had slowed to an almost stop. V2 then shunted forward and hit V3 because of the force of which they were hit by V1.

Severity SLIGHT Date: 11/09/2016 Sun 16:00 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 602V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	N -> S	0	male
	did not leave c'way	not requested	front		78
2 car	not at junction	stopping	N -> S	0	male
	did not leave c'way	not requested	back		41
3 car	not at junction	stopping	N -> S	0	male
	did not leave c'way	not requested	back		47

Casualty details Crash resulted in 4 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						78
driver/rider	SLIGHT					male
in veh 2						41
passenger	SLIGHT					female
in veh 2						42
passenger	SLIGHT					male
in veh 2						16

No.61 Road **A249** Section **179** Map ref: E586183 N163124 Parish: 197
District: Swale

Location **A249, MAIDSTONE ROAD, DANAWAY**

Description V2 travelling towards Sittingbourne on A249 when V2 broke down partially in the live lane 1 of 2. V1 collided with V2 causing damage to

V2 and minor injury to the driver of V2.

Severity SLIGHT Date: 16/09/2016 Fri 10:10 L Road Surface Dry Weather Fine Speed limit 70mph
Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	going ahead other	W -> E	0	male
	did not leave c'way	not requested	front		52
2 car	not at junction	parked	S -> N	0	female
	did not leave c'way	not requested	back		26

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						26

No.62 Road U Section Map ref: E586181 N162189 Parish: 31 District: Swale

Location **OAD STREET J/W ACCESS TO APPLGATE FARM**

Description V1 PULLED OUT OF JUNCTION ON TO OAD ST TURNING RIGHT. VIEW IS VERY RESTRICTED AND HAS A SHARP OFFSIDE BEND. V2 CAME ROUND BEND AND VEHICLES COLLIDED

Severity SLIGHT Date: 04/10/2016 Tue 10:30 L Road Surface Dry Weather Fine Speed limit 60mph

Single carriageway T or Staggered junction No Human control within 50m

Contributory Factors: 403V001A 405V001A 406V001A 307V002A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	turning right	S -> E	0	male
	did not leave c'way	negative	offside		66
2 car	approaching or parked on approach	going ahead other	E -> W	0	female
	did not leave c'way	negative	offside		62

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						66
driver/rider	SLIGHT					female
in veh 2						62
passenger	SLIGHT					female
in veh 1						43

No.63 Road A249 Section 176 Map ref: E585547 N162283 Parish: 270 District: Maidstone

Location **A249, 150 METRES NORTH OF STOCKBURY ROUNDABOUT**

Description A249 PRIOR TO STOCKBURY ROUNDABOUT. LIKELY THAT DRIVER OF V1 WAS NOT PAYING ATTENTION TO THE ROAD, DID NOT SEE V2 BRAKE IN FRONT OF THEM. WENT INTO THE BACK OF V2 CAUSING EXTENSIVE REAR DAMAGE AND PUSHED ONTO THE CURB.

Severity SLIGHT Date: 09/10/2016 Sun 15:25 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction No Human control within 50m

Contributory Factors: 406V001A 307V001A 308V001B 706V001B 405 V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods 3.5 - 7.5t	not at junction	stopping	NE -> SW	0	male
	did not leave c'way	not requested	front		32
2 car	not at junction	waiting to go ahead but held u	NE -> SW	0	female
	did not leave c'way	not requested	back		27
3 car	not at junction	waiting to go ahead but held u	NE -> SW	0	female
	did not leave c'way	not requested	back		37

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						32
driver/rider	SLIGHT					female
in veh 2						27
driver/rider	SLIGHT					female
in veh 3						37

No.64 Road **A249** Section **073** Map ref: E585344 N162028 Parish: 270
District: Maidstone

Location **A249, STOCKBURY ROUNDABOUT J/W M2**

Description V2 stationary on roundabout A249 Stockbury waiting to move off. Traffic to offside of V2 moved off and V1 struck the rear of V2

Severity SLIGHT Date: 11/10/2016 Tue 17:25 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 406V001A 601V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	entering roundabout	waiting to go ahead but held u	SW -> NE	0	not known
	did not leave c'way	not contacted	front		?
2 car	entering roundabout	waiting to go ahead but held u	SW -> NE	0	female
	did not leave c'way	not requested	back		30

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						30

No.65 Road **A249** Section **071** Map ref: E585281 N161822 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE ROAD, STOCKBURY VALLEY (MAPPED TO 585281,161822)**

Description 2 VEHICLE RTC, INJURY TO DRIVER & PASSENGER OF V2. INCIDENT OCCURRED IN HEAVY TRAFFIC WHILST V2 AS TRAVELLING TOWARDS STOCKBURY ROUNDABOUT FROM MAIDSTONE DIRECTION. WHEN V1 HAS PULLED OUT FROM A SIDE ROAD, OAD ST & ONTO V2'S PATH. SLIGHT DAMAGE, SLIGHT INJURY.

Severity SLIGHT Date: 08/11/2016 Tue 14:58 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 401V001B 405V001B 406V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	not at junction	starting	W -> E	0	male
	did not leave c'way	negative	nearside		76
2 car	not at junction	going ahead other	S -> N	0	female
	did not leave c'way	negative	offside		38

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						38
passenger	SLIGHT					male
in veh 2						39

No.66 Road **A249** Section Map ref: E584599 N161166 Parish: 270
District: Maidstone

Location **A249 SITTINGBOURNE RD J/W CHURCH HILL, STOCKBURY**

Description V1 was attempting to turn right from the A249 Maidstone bound into Church Hill, to either complete a U Turn or manoeuvre into Church Hill. V2 was travelling on the Sittingbourne bound A249 carriageway. V1 pulled out directly into the path of V2, causing the collision, and the damage and injuries listed.

Severity SLIGHT Date: 10/11/2016 Thu 07:07 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 405V001A 406V001A 403V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	waiting to turn right	E -> W	0	female
	did not leave c'way	not provided	nearside		39
2 car	approaching or parked on approach	going ahead other	SW -> NE	0	female
	did not leave c'way	negative	front		20

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						39
driver/rider	SLIGHT					female
in veh 2						20

No.67 Road **A249** Section **073** Map ref: E585356 N162085 Parish: 270
District: Maidstone

Location **A249, STOCKBURY ROUNDABOUT (MAPPED TO 585356,162085)**

Description V1 carrying out 'U' Turn on A249. V2 collided with V1. V3 then collided with V2. V1 failed to stop (No details known). Details passed by police between V2 and V3.

Severity SLIGHT Date: 02/12/2016 Fri 07:10 DRK NSL Road Surface Wet Weather Fine Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 403V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	starting	N -> W	0	not known
	did not leave c'way	not contacted	front		?
2 car	approaching or parked on approach	going ahead other	S -> N	0	male
	did not leave c'way	not contacted	offside		28
3 car	approaching or parked on approach	going ahead other	S -> N	0	male
	did not leave c'way	not contacted	offside		45

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						28

No.68 Road **A249** Section **068** Map ref: E584947 N161558 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE ROAD, NORTHBOUND (MAPPED TO 584947,161558)**

Description V2 travelling north bound along the A249 Stockbury in lane 2 of a possible 2 lanes. V3 travelling along same in lane 1. V1 filtering through traffic. V2 changes lane to the left colliding with V1. V1 consequently collided with V3.

Severity SERIOUS Date: 06/12/2016 Tue 16:57 DRK NSL Road Surface Wet Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 999V001A 405V002A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 m/cycle <= 50cc	not at junction	o/t moving vehicle on its O/S	SW -> NE	0	male
	did not leave c'way	not requested	front		29
2 car	not at junction	changing lane to left	SW -> NE	0	female
	did not leave c'way	not requested	nearside		24
3 car	not at junction	going ahead other	SW -> NE	0	male
	did not leave c'way	not requested	back		26

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						29

No.69 Road **A249** Section **070** Map ref: E585222 N161767 Parish: 270
District: Maidstone

Location **A249, DETLING HILL NEAR HONEYCROCK HILL (MAPPED TO 585210,161779)**

Description V2 travelling North on A249. V1 went into the back of V2. (D1 AGE UNKNOWN)

Severity SLIGHT Date: 16/01/2017 Mon 08:50 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	not at junction	waiting to go ahead but held u	SW -> NE	2	male
	did not leave c'way	not contacted	front		?
2 car	not at junction	waiting to go ahead but held u	SW -> NE	1	male
	did not leave c'way	not contacted	back		62

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						62

No.70 Road **A249** Section **073** Map ref: E585364 N162004 Parish: 270
District: Maidstone

Location **A249 SITTINGBOURNE ROAD, NORTH BOUND NEAR, STOCKBURY ROUNDABOUT**

Description 2 VEHICLE RTC ON APPROACH TO STOCKBURY ROUNDABOUT, SLIGHT DAMAGE, MINOR INJURY (MAPPED TO NEW CO-ORDINATES)

Severity SLIGHT Date: 17/01/2017 Tue 15:36 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 406V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	leaving main road	going ahead other	S -> N	2	male
	did not leave c'way	not requested	front		25
2 car	leaving main road	going ahead other	S -> N	1	male
	did not leave c'way	not requested	back		22

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					male
in veh 1						12

No.71 Road **A249** Section **176** Map ref: E585619 N162398 Parish: 31
District: Swale

Location **A249 STOCKBURY ROUNDABOUT, SOUTHBOUND, SITTINGBOURNE**

Description Both vehicles were travelling towards Stockbury on the A249 from the Sittingbourne direction. V2 was stationary in traffic when V1 struck the rear offside after swerving to avoid it.

Severity SLIGHT Date: 01/03/2017 Wed 11:45 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	negative	front		61
2 car	not at junction	stopping	NE -> SW	1	female
	did not leave c'way	negative	back		66

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						66

No.72

Road M2 Section 065

Map ref: E586539 N161810

Parish: 31

District: Swale

Location **M2 MP 66/0 'B' (MAPPED TO DESCRIPTION)**

Description All 3 vehicles were travelling in lane 2, M2 London Bound approaching Junction 5 slip off. Due to slip on further along the road, traffic has slowed. V3 was in front of V2, both which have braked. V2 has put on hazard lights. V1 has not stopped in time, and hit V2 in rear. This has pushed V2 into the rear of V3 causing it to spin off onto near-side verge, coming to rest on it's side.

Severity SLIGHT Date: 15/03/2017 Wed 08:49 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001B 406V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	2	male
	did not leave c'way	not requested	front		57
2 goods < 3.5t	not at junction	stopping	SE -> NW	1	male
	left c'way near-side	not requested	back		29
3 car	not at junction	stopping	SE -> NW	2	female
	did not leave c'way	not requested	back		41

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						29

No.73

Road A249 Section 176

Map ref: E585581 N162340

Parish: 31

District: Swale

Location **A249, 300 METRES NORTH OF JUNCTION WITH M2, SITTINGBOURNE**

Description All four vehicles travelling in a south-westerly direction on A249 towards Stockbury roundabout. V1 has braked sharply, causing V2 to do the same. To avoid a collision, V2 has steered away, colliding with V4 and V3. Injuries caused to two drivers.

Severity SERIOUS Date: 15/03/2017 Wed 14:00 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 307V001A 307V002B 405V001A

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	0	not known
	did not leave c'way	not contacted	did not impact		?
2 car	not at junction	going ahead other	NE -> SW	4	male
	did not leave c'way	negative	front		36
3 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	negative	back		38
4 car	not at junction	going ahead other	NE -> SW	3	male
	did not leave c'way	negative	back		44

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						36
driver/rider	SERIOUS					male
in veh 3						38

No.74

Road M2 Section 065

Map ref: E586156 N162015

Parish: 31

District: Swale

Location **M2 MP 65/6 SLIP OFF FOR JUNCTION 3 FOR A249 STOCKBURY**

Description Vehicles queued for junction 3 exit slip off, static traffic, v1 brakes hard and swerves. V1 appears to have swerved to avoid the queue of slowing traffic and has subsequently hit the kerb, lost control and flipped over onto its roof.

Severity SLIGHT Date: 19/03/2017 Sun 16:10 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
--------------	----------	----------	-----	---------	-----

registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	0	male
	did not leave c'way	not contacted	did not impact		19

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						19
passenger	SLIGHT					male
in veh 1						18

No.75 Road **A249** Section **064** Map ref: E584600 N161164 Parish: 270
District: Maidstone

Location **A249 SITTINGBOURNE RD J/W CHURCH HILL, STOCKBURY (MAPPED TO DESCRIPTION)**

Description V2 was waiting to turn from the turning point onto the A249 from the M2 direction. As they joined the A249 V1 would appear to have changed lanes from L1 to L2 causing the collision.

Severity SLIGHT Date: 21/03/2017 Tue 16:06 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 bus or coach	approaching or parked on approach	changing lane to right	SW -> NE	2	male
	did not leave c'way	negative	offside		53
2 car	approaching or parked on approach	u turn	NE -> NE	1	male
	did not leave c'way	negative	nearside		54

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT				Seated	male
in veh 1						77
passenger	SLIGHT				Seated	female
in veh 1						37
passenger	SLIGHT				Seated	female
in veh 1						12

No.76 Road **A249** Section **178** Map ref: E585911 N162830 Parish: 197
District: Swale

Location **A249, MAIDSTONE RD, SITTINGBOURNE (MAPPED TO COORDS).**

Description V1 WAS TRAVELLING TOWARDS STOCKBURY FROM SITTINGBOURNE ON A249, V2 WAS STATIONARY AT THE REAR OF STATIC TRAFFIC FROM THE RNDT. V1 BECAME AWARE OF STATIC TRAFFIC, HOWEVER WAS DISTRACTED BY OTHER STATIC TRAFFIC AND COLLIDED INTO REAR OF V2.

Severity SLIGHT Date: 11/04/2017 Tue 11:20 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NE -> SW	2	female
	did not leave c'way	negative	front		49
2 car	not at junction	waiting to go ahead but held u	NE -> SW	1	male
	did not leave c'way	negative	back		36

Casualty details Crash resulted in 4 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						49
driver/rider	SLIGHT					male
in veh 2						36
passenger	SLIGHT					female
in veh 2						35
passenger	SLIGHT					female
in veh 1						80

No.77 Road **A249** Section **176** Map ref: E585502 N162211 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE, (MAPPED TO DESCRIPTION).**

Description V2 was driving too fast towards the junction where the lights were red. V2 then braked very hard, causing the vehicle to dip. V1 was unable to stop in time and hit V2 from behind, pushing V2 further into the carriageway. V1 spun 180 degrees and came to a stop on the hard shoulder.

Severity SLIGHT Date: 23/04/2017 Sun 16:18 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 307V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	left c'way near-side	not contacted	front		56
2 car	not at junction	stopping	NE -> SW	1	male
	did not leave c'way	not contacted	back		65

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						56
passenger	SLIGHT					female
in veh 2						64

No.78 Road **A249** Section **176** Map ref: E585448 N162122 Parish: 270
District: Maidstone

Location **A249 J/W M2 (MAPPED TO DESCRIPTION. OLD COORDS:585329,162103)**

Description V1 travelling in nearside lane from Sittingbourne on A249 towards Stockbury roundabout J5, M2. V1 looked over to opposite carriageway believing they had seen a colleague driving in the opposite direction, turned back to see static traffic queuing at rndbt. V1 hit V2 nearside rear then left the carriageway. V2 pushed into V3. V2 written off. V3 slight damage to rear bumper.

Severity SERIOUS Date: 22/05/2017 Mon 15:59 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NE -> S	2	male
	did not leave c'way	negative	front		55
2 car	approaching or parked on approach	waiting to go ahead but held u	NE -> S	1	male
	did not leave c'way	negative	back		43
3 car	approaching or parked on approach	waiting to go ahead but held u	NE -> S	2	male
	did not leave c'way	negative	back		72

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						43
passenger	SERIOUS					male
in veh 2						39

No.79 Road **A249** Section **178** Map ref: E586122 N163046 Parish: 197
District: Swale

Location **A249 (MAPPED TO 586104,163055), SITTINGBOURNE.**

Description V1 and V2 travelling along A249, Maidstone bound. V2 has braked due to traffic ahead, V1 has collided with the rear of V2.

Severity SLIGHT Date: 24/05/2017 Wed 11:11 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	negative	front		74
2 car	not at junction	stopping	NE -> SW	1	female

did not leave c'way negative back 32

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement		school name	**to/from school	age
driver/rider	SLIGHT					female
in veh 2						32

No.80 Road **A249** Section **073** Map ref: E585393 N162008 Parish: 270
District: Maidstone

Location **A249, STOCKBURY ROUNDABOUT, STOCKBURY, SITTINGBOURNE**

Description V2 negotiating the roundabout in correct lane. V1 cut across path of V2. Collision occurred causing damage to both vehicles and minor injury to D2.

Severity SLIGHT Date: 01/06/2017 Thu 20:15 L Road Surface Dry Speed limit 50mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 401V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	changing lane to right	SE -> N	2	female
	did not leave c'way	negative	front		20
2 m/cycle > 500cc	mid junction	going ahead other	SE -> N	1	male
	did not leave c'way	negative	nearside		49

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement		school name	**to/from school	age
driver/rider	SLIGHT					male
in veh 2						49

No.81 Road **A249** Section **073** Map ref: E585405 N162002 Parish: 270
District: Swale

Location **A249 NEAR JN WITH STOCKBURY ROUNDABOUT**

Description V1 and V2 (cycle) were both on Stockbury Roundabout stationary at the traffic lights facing southbound A249 where the London bound M2 slips join the roundabout. V1 was in the left hand lane for A249 Maidstone. V2 was in the right hand lane for A249 Maidstone or M2 coast bound. As they moved off, V1 realised they needed to go right for the A249 Sittingbourne, and believed they were in the correct lane as signed posted A249. As V1 has turned right, V2 has continued towards Maidstone. V2 hit the driver's door of V1.

Severity SERIOUS Date: 13/06/2017 Tue 12:19 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 401V001A 403V001A 603V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	starting	NE -> W	2	female
	did not leave c'way	negative	offside		34
2 pedal cycle	mid junction	starting	NE -> SW	1	male
	did not leave c'way	not applicable	nearside		68

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement		school name	**to/from school	age
driver/rider	SERIOUS					male
in veh 2						68

No.82 Road **A249** Section **073** Map ref: E585396 N161997 Parish: 270
District: Maidstone

Location **A249 STOCKBURY RND BT J/W A249 SITTINGBOURNE RD, STOCKBURY**

Description V1 WAS NEGOTIATING THE ROUNDABOUT, WHILST CHANGING LANES COLLIDED WITH V2 CAUSING MINOR DAMAGE TO V2.

Severity SLIGHT Date: 19/06/2017 Mon 11:32 L Road Surface Dry Speed limit 60mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	leaving roundabout	changing lane to right	NE -> SW	2	male
	did not leave c'way	negative	front		69
2 car	leaving roundabout	going ahead other	NE -> SW	1	male
	did not leave c'way	negative	back		58

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
passenger	SLIGHT		school name			female
in veh 2						67

No.83 Road **M2** Section **264** Map ref: E585348 N162145 Parish: 270
District: Maidstone

Location **M2, STOCKBURY RNDBT J/W A249, SITTINGBOURNE.**

Description V2 and V3 have been stationary in traffic at the approach to the Stockbury roundabout, and V1 has crashed into the back of V2 causing V2 to shunt into the back of V3.

Severity SLIGHT Date: 09/07/2017 Sun 16:11 L Road Surface Dry Speed limit 70mph
Weather Fine

Slip road Roundabout
No Human control within 50m

Contributory Factors: 605V001A 308V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NE -> SE	2	male
	did not leave c'way	negative	front		19
2 car	approaching or parked on approach	waiting to go ahead but held u	NE -> SE	1	male
	did not leave c'way	negative	back		67
3 car	approaching or parked on approach	waiting to go ahead but held u	NE -> SE	2	male
	did not leave c'way	negative	back		40

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SLIGHT		school name			male
in veh 1						19
driver/rider	SLIGHT					male
in veh 2						67
driver/rider	SLIGHT					male
in veh 3						40
passenger	SLIGHT					female
in veh 2						61
passenger	SLIGHT					female
in veh 2						11

No.84 Road **A249** Section **068** Map ref: E584941 N161510 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE RD, O/S WHITE HOUSE, STOCKBURY VALLEY.**

Description V1 was driving Maidstone bound on the A249. D1 has clipped the kerb on the nearside which has caused the car to swerve. D1 has steered to counter this and the car has rolled onto the driver side. The car has slid into a wall at the bottom of someone's drive.

Severity SERIOUS Date: 23/07/2017 Sun 10:10 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Using private drive or entrance
No Human control within 50m

Contributory Factors: 306V001B 603V001A 409V001B 508V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NE -> SW	0	female
	left c'way near-side	not provided	offside		20

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SERIOUS		school name			female
in veh 1						20
passenger	SLIGHT					male
in veh 1						27

No.85 Road **A249** Section **176** Map ref: E585514 N162226 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE, (MAPPED TO COORDS)**

Description Vehicles were approaching Stockbury rmdbt and V1 hit rear of V2. V2 then impacted into rear of V3.

Severity SLIGHT Date: 09/08/2017 Wed 09:55 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	not requested	front		51
2 car	not at junction	stopping	NE -> SW	1	female
	did not leave c'way	not requested	back		28
3 car	not at junction	stopping	NE -> SW	2	male
	did not leave c'way	not requested	back		27

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						51
driver/rider	SLIGHT					female
in veh 2						28
passenger	SLIGHT					male
in veh 2						28

No.86 Road **A249** Section **069** Map ref: E585063 N161637 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE RD J/W HONEYCROCK HILL, STOCKBURY.**

Description V1 drove into V2 and admitted this at the scene. V2 was doing between 40-50 mph, other cars were slowing down and V1 went into the back of V2. D1 did provide their details at the scene. D2 has checked online and can see that V1 is not insured. (AGE UNKNOWN FOR V1)

Severity SLIGHT Date: 01/09/2017 Fri 17:21 L Road Surface Dry Weather Fine Speed limit 40mph

Single carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 406V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	cleared junction or parked at junction e	stopping	NE -> SW	2	male
	did not leave c'way	not contacted	front		?
2 car	cleared junction or parked at junction e	stopping	NE -> SW	1	female
	did not leave c'way	not contacted	back		27

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						27

No.87 Road **A249** Section **064** Map ref: E584618 N161164 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE RD J/W SLIP TO CHURCH HILL, STOCKBURY.**

Description V2 was travelling in lane 2 at approx 65/70 mph and could see a vehicle in lane 1 which appeared to be slowing. As V2 approached, V1 cut across them to take the exit last minute and crashed into V2.

Severity SERIOUS Date: 02/09/2017 Sat 20:01 DRK NSL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Slip Road
No Human control within 50m

Contributory Factors: 602V001A 403V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	leaving main road	changing lane to right	NE -> N	2	male
	did not leave c'way	negative	nearside		33
2 car	approaching or parked on approach	going ahead other	NE -> SW	1	male

did not leave c'way

negative

offside

32

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school		age
driver/rider	SLIGHT					male
in veh 1						33
driver/rider	SERIOUS					male
in veh 2						32
passenger	SLIGHT					female
in veh 2						32

No.88 Road **A249** Section **071** Map ref: E585277 N161817 Parish: 270 District: Maidstone

Location **A249 AT JN WITH OAD STREET, SITTINGBOURNE**

Description V1 has joined A249, heading towards Stockbury Roundabout, from OAD street. V2 has been travelling from Maidstone towards Stockbury Roundabout. V1 on pulling out of the waiting area in the central reservation, has driven into the side of V2.

Severity SLIGHT Date: 20/09/2017 Wed 15:50 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway T or Staggered junction No Human control within 50m

Contributory Factors: 403V001A 405V001A 406V001A 404V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	entering main road	turning right	SE -> NE	2	female
	did not leave c'way	not requested	front		60
2 bus or coach	mid junction	going ahead other	SW -> NE	1	male
	did not leave c'way	not requested	offside		49

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school		age
driver/rider	SLIGHT					female
in veh 1						60

No.89 Road **A249** Section **064** Map ref: E584610 N161160 Parish: 270 District: Maidstone

Location **A249 SITTINGBOURNE RD J/W HUCKING U TURN, STOCKBURY.**

Description V1 travelling north on the A249 and turning at the Hucking U-Turn when it collided with V2, which was travelling south towards Maidstone. All 4 persons travelling in V1 were injured. Three of them are classed as serious. D2 received minor injuries.

Severity SERIOUS Date: 30/09/2017 Sat 20:11 DRK USL Road Surface Wet Weather Rain Speed limit 70mph

Dual carriageway Other Junction No Human control within 50m

Contributory Factors: 403V001A 405V001A 406V001A 501V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 car	entering main road	u turn	SW -> SW	2	male
	did not leave c'way	not provided	nearside		19
2 car	mid junction	going ahead other	NE -> SW	1	male
	did not leave c'way	negative	front		29

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school		age
driver/rider	SERIOUS					male
in veh 1						19
driver/rider	SLIGHT					male
in veh 2						29
passenger	SERIOUS					male
in veh 1						20
passenger	SERIOUS					male
in veh 1						20
passenger	SERIOUS					male
in veh 1						18

No.90 Road **A249** Section **073** Map ref: E585440 N162017 Parish: 270 District: Maidstone

Location **A249 STOCKBURY ROUNDABOUT AT JN WITH A249, SITTINGBOURNE**

Description VEH 2 WAS DRIVING IN LANE 2 OF 2 ON THE STOCKBURY ROUNDABOUT MAIDSTONE BOUND. AS VEH 2 CAME OFF AT THE

JUNCTION FOR THE A249 MAIDSTONE, VEH 1, A LORRY WAS IN LANE1 OF 2 MAIDSTONE BOUND. VEH 1 DID NOT LEAVE FOR MAIDSTONE AND CONTINUED ROUND THE ROUNDABOUT FOR THE M2 COASTBOUND EXIT, HITTING VEH 2 AS THEY DID SO. VEH 1 STOPPED BLOCKING THE EXIT TO A249 MAIDSTONE. VEH 2 WAS PUSHED INTO THE GRASS AREA AND HIT A TEMPORARY SIGN. VEH 1 A FOREIGN DRIVER DID NOT ACCEPT IT WAS THEIR FAULT AND DID NOT SHARE THEIR DETAILS.

Severity SLIGHT Date: 03/10/2017 Tue 11:00 L Road Surface Dry Weather Fine Speed limit 30mph

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 606V001A 999V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	mid junction	going ahead right hand bend	NE -> NW	2	male
	did not leave c'way	not contacted	offside		?
2 car	leaving roundabout	going ahead right hand bend	NE -> SW	1	female
	left c'way Offside	not contacted	nearside		41

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						41

No.91 Road **M2** Section **064** Map ref: E585721 N162272 Parish: 31 District: Swale

Location **M2, MP 65/0 COASTBOUND, SIITINGBOURNE, (MAPPED TO COORDS).**

Description V2 BRAKED SHARPLY IN NEW ROADWORKS ON THE MOTORWAY, V1 HAS COLLIDED WITH V2. (V1 POSTCODE NOT KNOWN)

Severity SLIGHT Date: 06/10/2017 Fri 08:40 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 408V002A 308V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	male
	did not leave c'way	negative	front		34
2 car	not at junction	stopping	NW -> SE	1	female
	did not leave c'way	negative	back		84

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						84

No.92 Road **M2** Section **065** Map ref: E586341 N161933 Parish: 31 District: Swale

Location **M2, MARKER POST 65/9, B CARRIAGEWAY, SIITINGBOURNE.**

Description V1 HAS HESITATED AS TO WHICH LANE TO TAKE, HIT CONES OF CONTRAFLOW, DUMPED THE BIKE D1 WAS RIDING AND SLID UNDER WHEEL OF V2.

Severity SLIGHT Date: 09/10/2017 Mon 15:30 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 403V001A 107V001A 603V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 m/cycle 50 - 125cc	not at junction	changing lane to left	NW -> SE	0	male
	did not leave c'way	negative	front		51
2 goods > 7.5t	not at junction	going ahead other	NW -> SE	1	male
	did not leave c'way	negative	offside		37

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male

No.93Road **A249** Section **073**

Map ref: E585441 N162101

Parish: 270

District: Maidstone

Location **A249 STOCKBURY RNDBT J/W M2, SITTINGBOURNE**

Description V2 PULLED UP TO STOCKBURY ROUNDABOUT MAIDSTONE BOUND FROM SITTINGBOURNE. V2 WAS WAITING AT THE TRAFFIC LIGHTS WHEN V1 REAR ENDED V2.

Severity SLIGHT Date: 11/11/2017 Sat 05:00 DRK STL Road Surface Wet Weather Rain Speed limit 70mph

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 501V001B 103V001B 410V001B 602V001B 901 V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	entering roundabout	waiting to go ahead but held u	NE -> S	2	male
	did not leave c'way	not requested	front		28
2 car	entering roundabout	stopping	NE -> S	1	male
	did not leave c'way	not requested	back		38

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SLIGHT					male
in veh 2						38

No.94Road **A249** Section **073**

Map ref: E585360 N162026

Parish: 270

District: Maidstone

Location **A249 J/W STOCKBURY ROUNDABOUT, SITTINGBOURNE**

Description V1 was travelling onto Stockbury Roundabout from A249 Maidstone and intending to travel A249 towards Sittingbourne. V2 was travelling onto the roundabout from the M2 Coastbound carriageway. Whilst both vehicles were on the roundabout they collided when V1 clipped the rear of V2. No independant witnesses .

Severity SLIGHT Date: 16/11/2017 Thu 12:35 L Road Surface Dry Weather Fine Speed limit 70mph

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 406V001A 406V002A 605V001A 405 V002A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 m/cycle 50 - 125cc	entering roundabout	going ahead other	S -> NW	2	male
	did not leave c'way	negative	front		27
2 goods < 3.5t	mid junction	going ahead other	SE -> NW	1	male
	did not leave c'way	negative	back		47

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SLIGHT					male
in veh 1						27

No.95Road **A249** Section **069**

Map ref: E585057 N161647

Parish: 270

District: Maidstone

Location **A249, SITTINGBOURNE (ORIGINAL COORDS - 585063,161637)**

Description V1, FOREIGN VEHICLE HAS COLLIDED WITH V2, SPINNING V2 AROUND.

Severity SLIGHT Date: 24/11/2017 Fri 17:08 DRK STL Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	going ahead other	SW -> NE	2	male
	did not leave c'way	not contacted	nearside		44
2 car	not at junction	going ahead other	SW -> NE	1	male
	did not leave c'way	not contacted	front		31

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						31

No.96 Road **A249** Section **176** Map ref: E585547 N162282 Parish: 270
District: Maidstone

Location **A249, MAIDSTONE RD, SITTINGBOURNE, (MAPPED TO COORDS).**

Description V1 and V2 travelling SW along A249 towards Stockbury roundabout. V2 slowly moving in traffic when V1 tried to overtake to enter the outer lane - hitting rear V2. No witnesses. Details gained. V2 driver injuries. CCTV present.

Severity SLIGHT Date: 30/12/2017 Sat 12:30 L Road Surface Dry Speed limit 40mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 403V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 goods < 3.5t	not at junction	changing lane to left	NE -> SW	2	not known
	did not leave c'way	not contacted	front		?
2 car	not at junction	stopping	NE -> SW	1	female
	did not leave c'way	not contacted	back		21

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						21

No.97 Road **A249** Section **073** Map ref: E585457 N162041 Parish: 270
District: Maidstone

Location **A249 STOCKBURY RNDT J/W M2, SITTINGBOURNE (MAPPED TO DESC. ORIGINAL COORDS - 585477,162012)**

Description V1, FOREIGN REGISTERED LEFT HAND HGV WAS FOLLOWING THEIR SAT NAV AND THE ROAD MARKINGS TOWARDS THE M2 DOVER. V2 WAS IN LANE 2 TRAVELLING TOWARDS MAIDSTONE. V1 FOLLOWED THE LANE AROUND THE RNDT AND COLLIDED WITH V2 AS V2 ATTEMPTED TO LEAVE THE RNDT.

Severity SLIGHT Date: 16/01/2018 Tue 06:34 DRK STL Road Surface Wet Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 405V001B 406V001B 405V002B 406V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration	b-test		1st hit	damaged	age
1 goods > 7.5t	leaving roundabout	going ahead right hand bend	NW -> S	2	male
	did not leave c'way	not contacted	offside		49
2 car	mid junction	going ahead right hand bend	NW -> S	1	male
	did not leave c'way	not contacted	nearside		30

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						30
passenger	SLIGHT					male
in veh 2						46

No.98 Road **A249** Section **073** Map ref: E585432 N162086 Parish: 270
District: Maidstone

Location **A249 STOCKBURY RNDT J/W A249 MAIDSTONE RD, STOCKBURY**

Description V1 AND V2 WERE BOTH NEGOTIATING THE RNDT AND COLLIDED WITH EACH OTHER.

Severity SLIGHT Date: 16/01/2018 Tue 08:00 L Road Surface Wet Speed limit 70mph
Weather Rain

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001B 405V001B 405V002B 406V002B 710 V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
--------------	----------	----------	-----	---------	-----

registration		b-test	1st hit	damaged	age
1 goods > 7.5t	mid junction	going ahead other	NW -> SE	2	male
	did not leave c'way	negative	nearside		30
2 car	mid junction	going ahead other	NW -> SE	1	female
	did not leave c'way	negative	offside		28

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SLIGHT					female
in veh 2						28

No.99 Road **A249** Section **073** Map ref: E585354 N162056 Parish: 270
District: Maidstone

Location **A249 RNDBT J/W M2, STOCKBURY (MAPPED TO DESC. ORIGINAL COORDS - 585349,162079)**

Description V1 was in lane 3 of 3 and was attempting to move across into lane 2, as V1 began the manoeuvre D1 has not seen V2 and V2 has then collided into the rear nearside of V1 and after a couple of metres has come to a halt.

Severity SLIGHT Date: 05/02/2018 Mon 16:07 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A 405V002A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	changing lane to left	SE -> NE	2	male
	did not leave c'way	negative	nearside		31
2 goods > 7.5t	mid junction	going ahead right hand bend	SE -> NE	1	male
	did not leave c'way	negative	front		20

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
passenger	SLIGHT					male
in veh 1						29

No.100 Road **A249** Section **176** Map ref: E585427 N162123 Parish: 270
District: Maidstone

Location **A249, SITTINGBOURNE RD J/W MAIDSTONE RD, STOCKBURY.**

Description REPORTED BY D2. V2 EXITING OFF STOCKBURY RNDBT ONTO A249 MAIDSTONE RD, WHEN V1 DROVE ALONGSIDE THEIR OFFSIDE WITHOUT ENOUGH ROOM. V2 COULD NOT MOVE OVER DUE TO TRAFFIC COMING ONTO ROAD FROM M2. THEREFORE THEY COLLIDED, SECTION 170 COMPLIED, CCTV CAMERA ON FRONT INDICATORS AND IN CAB AND REAR OF V2. V2 DRIVER INJURED, NO WITNESS DETAILS.

Severity SLIGHT Date: 22/02/2018 Thu 16:50 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 406V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	leaving roundabout	going ahead other	NE -> N	2	male
	did not leave c'way	not contacted	nearside		70
2 goods < 3.5t	leaving roundabout	going ahead other	NE -> N	1	male
	did not leave c'way	not contacted	offside		52

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement			**to/from school	age
driver/rider	SLIGHT					male
in veh 2						52

No.101 Road **A249** Section **073** Map ref: E585444 N162101 Parish: 270
District: Maidstone

Location **A249, MAIDSTONE RD J/W STOCKBURY RNDBT J/W M2, STOCKBURY.**

Description V1 got to junction 5 and sat at the traffic lights. V1 was shunted forward by V2. Car spun round onto the on coming lane. Car then hit V2 again. (AGE FOR V1 NOT KNOWN).

Severity SLIGHT Date: 27/02/2018 Tue 08:05 L Road Surface Snow Speed limit 70mph
Weather Snow

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	stopping	NE -> SW	2	male
	did not leave c'way	not contacted	back		?
2 goods < 3.5t	approaching or parked on approach	stopping	NE -> SW	1	male
	did not leave c'way	not contacted	front		48

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						48

No.102 Road **M2** Section **064** Map ref: E585303 N162482 Parish: 31
District: Swale

Location **M2 B CARRIAGEWAY MP 64/2, STOCKBURY (MAPPED TO DESC. ORIGINAL COORDS - 585908,162139)**

Description V1 travelling London bound on M2 has for reasons unknown lost control and overturned.

Severity SLIGHT Date: 02/04/2018 Mon 05:20 DRK STL Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 410V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	0	female
	left c'way nearside & rebounded	not requested	front		81

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						81

No.103 Road **M2** Section **264** Map ref: E585870 N162125 Parish: 31
District: Swale

Location **M2 B CARRIAGEWAY OFFSLIP, STOCKBURY (MAPPED TO COORDS)**

Description All vehicles involved had been travelling on the M2 taking J5 slip off for A249. V2 has stopped due to another vehicle in front losing control on spilt fuel. V1 has collided into rear of V2. V3 has then collided into the rear of V2. V4 has then collided into both V1 and V3.

Severity SLIGHT Date: 08/04/2018 Sun 07:25 DRK NSL Road Surface Wet Speed limit 70mph
Weather Rain

Slip road Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 102V001A

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead left hand bend	E -> SW	2	male
	did not leave c'way	negative	front		55
2 car	not at junction	going ahead left hand bend	E -> SW	1	male
	did not leave c'way	negative	back		55
3 car	not at junction	going ahead left hand bend	E -> SW	2	female
	did not leave c'way	negative	front		54
4 car	not at junction	going ahead left hand bend	E -> SW	1	male
	did not leave c'way	negative	offside		58

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						55
passenger	SLIGHT					female
in veh 2						55

No.104 Road **M2** Section **064** Map ref: E585192 N162550 Parish: 197
District: Swale

Location **M2, MARKER POST 64/1, B CARRIAGEWAY, JUNCTIONS 5-4, SITTINGBOURNE.**

Description V1 IS HGV UNLADEN, D1 FELT THE REAR END SLIDE, THEY TRIED TO CORRECT IT, BUT VEHICLE JACKKNIFED HITTING CENTRAL RESERVATION AND TREES ON SIDE OF THE MOTORWAY.

Severity SLIGHT Date: 13/04/2018 Fri 05:50 L Road Surface Wet Speed limit 70mph
Weather Fog Mist

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001A 101V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	going ahead other	SE -> NW	0	female
	left c'way offside onto central res.	negative	front		27

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						27

No.105 Road **A249** Section **073** Map ref: E585362 N162015 Parish: 270
District: Maidstone

Location **A249 STOCKBURY ROUNDABOUT AT JN WITH M2 CANTERBURY SLIP ON (MAPPED TO DESCRIPTION, ORIGINAL CO-ORDS 585445, 162082)**

Description V2 STATIONARY AT RDNBT. V1 COLLIDED INTO REAR OF V2 BUMPING AND SHUNTING VEHICLE TWICE.

Severity SLIGHT Date: 16/04/2018 Mon 13:54 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 307V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	approaching or parked on approach	going ahead other	SW -> NE	2	not known
	did not leave c'way	not contacted	front		?
2 car	approaching or parked on approach	going ahead other	SW -> NE	1	female
	did not leave c'way	not contacted	back		39

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						39

No.106 Road **A249** Section **071** Map ref: E585288 N161804 Parish: 270
District: Maidstone

Location **A249 SITTINGBOURNE ROAD J/W OAD STREET, MAIDSTONE**

Description Appears that V2 has crossed the A249 from Oad Street and has been struck by V1 travelling on the A249 towards Maidstone. Driver of V2 has suffered fatal injuries.

Severity FATAL Date: 24/04/2018 Tue 06:30 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 403V002B 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NE -> SW	2	male
	left c'way offside onto central res. & ret	negative	front		35
2 car	mid junction	turning right	SE -> NE	1	female
	left c'way offside onto central res. & ret	not provided	offside		61

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	FATAL					female
in veh 2						61

No.107 Road **M2** Section **065** Map ref: E585468 N162003 Parish: 31
District: Maidstone

Location **M2 LONDONBOUND SLIP OFF J5 J/W A249 RNDBT, STOCKBURY**

Description V1 travelling londonbound on M2, takes exit slip at Junction 5. V1 then fails to reduce speed, striking Armco on the nearside. V1 has then impacted with V2, V3 and V4 before coming to rest in the carriageway of Stockbury roundabout.

Severity SERIOUS Date: 06/05/2018 Sun 13:33 L Road Surface Dry Weather Fine Speed limit 70mph

Slip road Roundabout
No Human control within 50m

Contributory Factors: 410V001A 203V001B 505V001B

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach left c'way nearside & rebounded	going ahead right hand bend	NE -> W	2	male
		not provided	front		81
2 car	approaching or parked on approach did not leave c'way	going ahead right hand bend	NE -> W	1	male
		negative	back		39
3 car	approaching or parked on approach did not leave c'way	going ahead right hand bend	NE -> W	1	male
		negative	front		73
4 car	mid junction did not leave c'way	going ahead other	NE -> S	1	female
		negative	nearside		70

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						81
passenger	SERIOUS					female
in veh 1						82

No.108 Road M2 Section 064 Map ref: E585103 N162615 Parish: 197 District: Swale

Location **M2 COASTBOUND NEAR JUNCTION 5 OFFSLIP, STOCKBURY (MAPPED TO COORDS)**

Description V3 slowed due to heavy traffic ahead. V2 slowed down and then was hit by V1 from behind at approx 70 mph which caused V2 to hit the rear of V3.

Severity SLIGHT Date: 07/05/2018 Mon 09:15 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 510V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction did not leave c'way	going ahead other	NW -> SE	2	female
		not requested	front		52
2 car	not at junction did not leave c'way	stopping	NW -> SE	1	female
		not requested	back		31
3 car	not at junction did not leave c'way	stopping	NW -> SE	2	female
		not requested	back		59

Casualty details Crash resulted in 3 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 1						52
driver/rider	SLIGHT					female
in veh 2						31
passenger	SLIGHT					female
in veh 1						31

No.109 Road M2 Section 064 Map ref: E585307 N162480 Parish: 31 District: Swale

Location **M2 B CARRIAGEWAY MP 64/2, STOCKBURY (MAPPED TO DESC. ORIGINAL COORDS - 585375,162439)**

Description V1 TRAVELLING LONDON BOUND ON M2, V1 WAS UNABLE TO SLOW FOR MOVING TRAFFIC AHEAD. V1 TOOK AVOIDING ACTION TO PREVENT COLLIDING WITH SLOWING TRAFFIC AND IN SO DOING LEFT CARRIAGEWAY TO NEAR SIDE, TRAVELLED UP EMBANKMENT AND OVERTURNED.

Severity SERIOUS Date: 07/05/2018 Mon 08:35 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	0	male
	left c'way near-side	negative	front		21

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					male
in veh 1						21
passenger	SLIGHT					male
in veh 1						23

No.110 Road **M2** Section **064** Map ref: E585128 N162575 Parish: 197
District: Swale

Location **M2 MP 63/8 B CARRIAGE WAY STOCKBURY (MAPPED TO NEW COORDINATES; ORIGINAL COORDINATES 582769, 163591)**

Description V1 hit V2 in the rear in slow moving traffic.

Severity SLIGHT Date: 08/05/2018 Tue 10:47 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	2	female
	did not leave c'way	negative	front		27
2 car	not at junction	stopping	E -> W	1	female
	did not leave c'way	negative	back		24

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						24
passenger	SLIGHT					female
in veh 1						3

No.111 Road **M2** Section **065** Map ref: E586326 N161924 Parish: 31
District: Swale

Location **M2, MARKER POST 65/7, B CARRIAGEWAY, SITTINGBOURNE.**

Description V2 was travelling in lane 1 of 2 - was hit from behind by V1.

Severity SLIGHT Date: 29/05/2018 Tue 15:30 L Road Surface Wet Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods < 3.5t	not at junction	going ahead other	SE -> NW	2	male
	did not leave c'way	negative	front		35
2 car	not at junction	going ahead other	SE -> NW	1	male
	did not leave c'way	not requested	back		75

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						75

No.112 Road **A249** Section **073** Map ref: E585360 N162016 Parish: 270
District: Maidstone

Location **A249, STOCKBURY RDNDBT J/W M2, SITTINGBOURNE. (MAPPED TO DESCRIPTION, ORIGINAL COORDINATES 585340, 162043)**

Description V2 WAS STATIONARY AT STOCKBURY ROUNDABOUT ON A249 WHEN STRUCK FROM BEHIND BY V1.

Severity SLIGHT Date: 19/06/2018 Tue 07:40 L Road Surface Dry Weather Fine Speed limit 70mph

Roundabout

Roundabout
No Human control within 50m

Contributory Factors: 405V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	S -> N	2	male
	did not leave c'way	negative	front		28
2 m/cycle > 500cc	entering roundabout	waiting to go ahead but held u	SE -> N	1	male
	did not leave c'way	negative	back		38

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						38

No.113 Road **A249** Section **176** Map ref: E585443 N162117 Parish: 270
District: Maidstone

Location **A249 MAIDSTONE RD, STOCKBURY (MAPPED TO COORDS)**

Description V1, V2 and V3 were travelling southwest on Maidstone Rd towards Stockbury rndbt in lane 2. V3 and V2 had slowed to a stop not far from traffic lights due to traffic ahead. V1 did not stop in time and collided with the rear of V2, which was shunted forwards into the rear of V3.

Severity SERIOUS Date: 08/07/2018 Sun 16:00 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 307V001A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	female
	did not leave c'way	negative	front		41
2 car	not at junction	stopping	NE -> SW	1	female
	did not leave c'way	negative	back		37
3 car	not at junction	stopping	NE -> SW	2	female
	did not leave c'way	negative	back		34

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SERIOUS					female
in veh 2						37

No.114 Road **M2** Section **064** Map ref: E585093 N162618 Parish: 197
District: Swale

Location **M2, MP 64/0, STOCKBURY (MAPPED TO COORDS)**

Description All vehicles were in lane 1, on the motorway travelling coast bound when traffic ahead of them came to a stop. All vehicles managed to stop safely and in time apart from V1 which was unable to stop and crashed into the rear of V2 with such speed that it caused a knock-on collision involving 3 other vehicles. V1 failed to stop and sped off.

Severity SLIGHT Date: 03/08/2018 Fri 11:00 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001A 406V001A 308V001A 307V001A 999 V001A

Vehicle details Crash involved 5 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	not known
	did not leave c'way	not contacted	front		?
2 car	not at junction	stopping	NW -> SE	1	female
	did not leave c'way	not contacted	back		28
3 goods < 3.5t	not at junction	stopping	NW -> SE	2	male
	did not leave c'way	not contacted	back		22
4 car	not at junction	stopping	NW -> SE	3	male
	did not leave c'way	not contacted	back		42
5 car	not at junction	stopping	NW -> SE	4	female
	did not leave c'way	not contacted	back		30

Casualty details Crash resulted in 4 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
-------	----------	---------------------	-----	-----------	---------------	-----

	pedestrian movement	school name	**to/from school	age
driver/rider	SLIGHT			female
in veh 2				28
passenger	SLIGHT			female
in veh 2				16
passenger	SLIGHT			male
in veh 2				7
passenger	SLIGHT			male
in veh 2				24

No.115 Road **A249** Section **073** Map ref: E585365 N162018 Parish: 270
District: Maidstone

Location **A249 SITTINGBOURNE RD J/W STOCKBURY RNCDBT, STOCKBURY (MAPPED TO DESC. ORIGINAL COORDS - 585356,162085)**

Description V1 WAS IN LANE 2 ON SITTINGBOURNE RD AT THE JUNCTION WITH STOCKBURY RNCDBT. VISIBILITY WAS REDUCED DUE TO SUN GLARE. V1 SLOWLY PULLED OUT ONTO THE RNCDBT, BELIEVING IT WAS CLEAR, AND MADE CONTACT WITH THE REAR NEARSIDE OF V2, CAUSING R2 TO COME OFF THE VEHICLE. (AGE FOR V2 / C1 NOT KNOWN)

Severity SLIGHT Date: 07/09/2018 Fri 07:30 L Road Surface Dry Speed limit 60mph
Weather Fine

Dual carriageway Roundabout
No Human control within 50m

Contributory Factors: 402V001A 706V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	entering roundabout	starting	S -> NW	2	male
	did not leave c'way	negative	front		42
2 m/cycle > 500cc	mid junction	going ahead right hand bend	SE -> N	1	male
	did not leave c'way	negative	nearside		?

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school	age	
driver/rider	SLIGHT					male
in veh 2						?

No.116 Road **A249** Section **073** Map ref: E585411 N162002 Parish: 270
District: Maidstone

Location **A249 STOCKBURY RNCDBT J/W A249 SITTINGBOURNE RD, STOCKBURY.**

Description V1 travelling from Sittingbourne on A249 towards Dover using the roundabout, V2 travelling from Sittingbourne on A249 towards Maidstone. V1 in lane 1, V2 in lane 2. V1 has gone around the roundabout and V2 has collided with side of V1 as it has been in the wrong lane.

Severity SLIGHT Date: 23/09/2018 Sun 16:30 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	mid junction	stopping	NE -> W	2	male
	did not leave c'way	negative	offside		43
2 car	mid junction	stopping	NE -> SW	1	male
	did not leave c'way	negative	front		30

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name	**to/from school	age	
driver/rider	SLIGHT					male
in veh 2						30

No.117 Road **A249** Section **069** Map ref: E585087 N161662 Parish: 270
District: Maidstone

Location **A249 DETLING J/W HONEYCROCK HILL, STOCKBURY**

Description V2 WAS STATIONARY ON A249 WHEN V1 COLLIDED WITH THE REAR OF V2.

Severity SLIGHT Date: 10/10/2018 Wed 16:59 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NE -> SW	2	female
	did not leave c'way	not contacted	front		53
2 car	leaving main road	waiting to turn right	NE -> NW	1	female
	did not leave c'way	not contacted	back		41

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						41

No.118 Road **M2** Section **063** Map ref: E584761 N162783 Parish: 197
District: Swale

Location **M2 B, CARRIAGEWAY HARTLIP (MAPPED TO NEW COORDINATES, ORIGINAL COORDINATES 584766, 162787)**

Description D1 and D2 could not recall the details of the collision. It appears that V1 had collided with back of V2 before coming off the carriageway to the nearside onto a grassy bank. V2 collided heavily with the central reservation before stopping sideways in lane 2 of 2.

Severity SLIGHT Date: 14/10/2018 Sun 20:13 DRK STL Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001B 405V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	SE -> NW	2	male
	left c'way near-side	not requested	front		43
2 car	not at junction	going ahead other	SE -> NW	1	female
	left c'way near-side	not requested	back		52

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					female
in veh 1						14
passenger	SLIGHT					female
in veh 1						17
passenger	SLIGHT					female
in veh 1						49
driver/rider	SLIGHT					male
in veh 1						43
driver/rider	SLIGHT					female
in veh 2						52

No.119 Road **M2** Section **065** Map ref: E586355 N161904 Parish: 31
District: Swale

Location **M2, B CARRIAGEWAY, MARKER POST 65/3, BORDEN (MAPPED TO NEW COORDINATES, ORIGINAL COORDINATES 584158, 163116)**

Description V1 (which is currently unknown) brakes suddenly in front of V2. V2 avoids colliding with V1, however V3 does not brake sufficiently in time to avoid colliding with V2.

Severity SLIGHT Date: 25/10/2018 Thu 11:19 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 408V001A 406V002A 406V003A

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	SE -> NW	0	not known
	did not leave c'way	not contacted	did not impact		?
2 car	not at junction	stopping	SE -> NW	3	female
	did not leave c'way	negative	back		33
3 car	not at junction	stopping	SE -> NW	2	male
	did not leave c'way	negative	front		56

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						33

driver/rider in veh 3	SLIGHT	male 56
--------------------------	--------	------------

No.120 Road **M2** Section **064** Map ref: E585157 N162586 Parish: 197
District: Swale

Location **M2, A CARRIAGEWAY J/W J5, HARTLIP.**

Description V1 was travelling in lane 1 coast-bound approaching Jct 5 off slip, when the vehicle moved in a sharp right turn/moved right and drove into the central reservation, rebounding into the carriageway coming to a stop across lanes 1 & 2.

Severity SERIOUS Date: 31/10/2018 Wed 15:28 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Slip Road
No Human control within 50m

Contributory Factors: 503V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	approaching or parked on approach	going ahead other	NW -> SE	0	male
	left c'way offside onto central res.	not provided	front		27

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SERIOUS					male 27

No.121 Road **A249** Section **066** Map ref: E584790 N161329 Parish: 270
District: Maidstone

Location **A249 J/W C84 SOUTH GREEN LANE, STOCKBURY**

Description V1 was in lane 2 of the B carriageway on the A249. V2 was waiting at the gap in the central reservation to cross the A249 into South Green Lane. V1 aquaplaned and skidded on the wet road clipping the front of V2. V1 then continued out of control, mounting the metal barrier and colliding with a sign post, bringing V1 to a stop.

Severity SLIGHT Date: 01/11/2018 Thu 07:32 L Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway T or Staggered junction
No Human control within 50m

Contributory Factors: 307V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	mid junction	going ahead right hand bend	NE -> SW	2	male
	left c'way offside onto central res.	negative	front		31
2 car	approaching or parked on approach	waiting to turn right	SW -> SE	1	female
	did not leave c'way	not contacted	nearside		36

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 31

No.122 Road **M2** Section **264** Map ref: E585853 N162126 Parish: 31
District: Swale

Location **M2, J5, B CARRIAGEWAY OFF SLIP, STOCKBURY.**

Description V1 APPEARS TO HAVE LOST CONTROL ON SLIP RD AND OVERTURNED. D1 WAS TRAPPED AND SUFFERED SERIOUS INJURY.

Severity SERIOUS Date: 29/11/2018 Thu 05:40 DRK STL Road Surface Wet Speed limit 70mph
Weather Rain

Slip road Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 103V001B 307V001A 408V001B

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	going ahead left hand bend	SE -> SW	0	male
	left c'way Offside	not requested	offside		42

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age

driver/rider	SERIOUS	male
in veh 1		42

No.123 Road **A249** Section **065** Map ref: E584720 N161249 Parish: 270
District: Maidstone

Location **A249 DETLING HILL, STOCKBURY (MAPPED TO COORDS)**

Description V2 WAS TRAVELLING NORTHEAST ON DETLING HILL AND STARTED TO SLOW DOWN DUE TO TRAFFIC. D2 PUT THEIR HAZARD LIGHTS ON TO WARN OTHER DRIVERS. D1, TRAVELLING BEHIND, ALSO STARTED TO SLOW DOWN AND PUT THEIR HAZARD LIGHTS ON BUT DID NOT REACT QUICK ENOUGH AND COLLIDED WITH THE REAR OF V2.

Severity SLIGHT Date: 14/01/2019 Mon 17:59 DRK NSL Road Surface Dry Weather Fine Speed limit 60mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 408V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	stopping	SW -> NE	2	male
	did not leave c'way	negative	front		67
2 car	not at junction	stopping	SW -> NE	1	male
	did not leave c'way	negative	back		29

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						67
driver/rider	SLIGHT					male
in veh 2						29

No.124 Road **A249** Section **073** Map ref: E585408 N162001 Parish: 270
District: Maidstone

Location **A249 STOCKBURY RNDBT J/W A249 SITTINGBOURNE RD, STOCKBURY**

Description V1 was in the left-hand lane and V2 was in the right-hand lane. V2 was intending to travel straight ahead onto Sittingbourne Rd but V1 turned around the rndbt and collided with the nearside rear passenger door of V2, causing V2 to spin 180 degrees in road.

Severity SLIGHT Date: 07/02/2019 Thu 08:05 L Road Surface Dry Weather Fine Speed limit 70mph

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 710V001A 403V001B 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	mid junction	going ahead right hand bend	NE -> NW	2	male
	did not leave c'way	negative	offside		42
2 car	leaving roundabout	going ahead left hand bend	NE -> S	1	female
	did not leave c'way	negative	nearside		47

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger	SLIGHT					male
in veh 2						52
driver/rider	SLIGHT					female
in veh 2						47

No.125 Road **A249** Section **176** Map ref: E585535 N162263 Parish: 270
District: Maidstone

Location **A249, MAIDSTONE RD, STOCKBURY, (MAPPED TO COORDS).**

Description TRAFFIC SLOWING FOR RED ATS AT STOCKBURY ROUNDABOUT, A249 MAIDSTONE BOUND. V1 HAS FAILED TO ANTICIPATE SLOWING TRAFFIC AND COLLIDED WITH REAR OF V2. V2 HAS THEN HIT V3.

Severity SLIGHT Date: 19/02/2019 Tue 14:18 L Road Surface Dry Weather Fine Speed limit 70mph

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 308V001B 405V001B

Vehicle details Crash involved 3 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male

2 car	did not leave c'way not at junction	negative stopping	front	NE -> SW	1	21 male
3 car	did not leave c'way not at junction	negative stopping	back	NE -> SW	2	41 male
	did not leave c'way	negative	back			54

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 21
driver/rider in veh 2	SLIGHT					male 41
driver/rider in veh 3	SLIGHT					male 54
passenger in veh 2	SLIGHT					male 6
passenger in veh 2	SLIGHT					male 8

No.126 Road **M2** Section **065** Map ref: E585996 N162097 Parish: 31
District: Swale

Location **M2 J5 OFF SLIP J/W M2, STOCKBURY VALLEY.**

Description SINGLE VEHICLE RTC. D1 HAS LOST CONTROL OF VEHICLE. VEERED OFF CARRIAGEWAY AND INTO DITCH. SLIGHT INJURY.

Severity SLIGHT Date: 02/03/2019 Sat 20:00 DRK STL Road Surface Wet Speed limit 70mph
Weather Rain

Slip road Slip Road
No Human control within 50m

Contributory Factors: 410V001A 403V001A 307V001A

Vehicle details Crash involved 1 vehicle

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	cleared junction or parked at junction e	turning left	SE -> SW	0	male
	left c'way near-side	negative	front		40

Casualty details Crash resulted in 5 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 40
passenger in veh 1	SLIGHT					female 50
passenger in veh 1	SLIGHT					male 7
passenger in veh 1	SLIGHT					male 13
passenger in veh 1	SLIGHT					male 13

No.127 Road **A249** Section **073** Map ref: E585443 N162077 Parish: 270
District: Maidstone

Location **A249 MAIDSTONE RD J/W A249 STOCKBURY RNBDBT, STOCKBURY**

Description V1 entered the rndbt in lane 1 intending to turn right towards the M2. V2 entered the rndbt in lane 2 intending to go straight ahead towards the A249. As V2 passed the inside of V1, V1 collided with V2's nearside causing it to spin.

Severity SLIGHT Date: 11/03/2019 Mon 20:01 DRK STL Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A 508V001B 307V002A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	entering roundabout	going ahead left hand bend	NE -> SE	2	male
	did not leave c'way	negative	front		34
2 car	entering roundabout	going ahead right hand bend	NE -> SE	1	female
	left c'way near-side	not requested	nearside		29

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 1	SLIGHT					male 34

driver/rider in veh 2	SLIGHT	female 29
--------------------------	--------	--------------

No.128 Road **M2** Section **063** Map ref: E584711 N162825 Parish: 197
District: Swale

Location **M2 A CARRIAGEWAY, DANAWAY (MAPPED TO COORDS)**

Description V1 COLLIDED WITH THE REAR OF V2, CAUSING V2 TO COLLIDE WITH THE REAR OF V3, V3 WITH THE REAR OF V4, V4 WITH THE REAR OF V5 AND V5 WITH THE REAR OF V6.

Severity SLIGHT Date: 11/03/2019 Mon 07:09 L Road Surface Dry Speed limit 70mph
Weather Fine Wind

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 406V001A 406V002A 406V003A 406V004A 406 V005A 406V006A

Vehicle details Crash involved 6 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NW -> SE	2	female
	did not leave c'way	negative	front		27
2 car	not at junction	going ahead other	NW -> SE	1	male
	did not leave c'way	negative	back		55
3 car	not at junction	going ahead other	NW -> SE	2	male
	did not leave c'way	negative	back		35
4 car	not at junction	going ahead other	NW -> SE	3	male
	did not leave c'way	negative	back		31
5 goods < 3.5t	not at junction	going ahead other	NW -> SE	4	male
	did not leave c'way	negative	back		31
6 car	not at junction	going ahead other	NW -> SE	5	female
	did not leave c'way	negative	back		34

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider in veh 5	SLIGHT					male 31
passenger in veh 4	SLIGHT					female 25

No.129 Road **A249** Section **176** Map ref: E585509 N162252 Parish: 270
District: Maidstone

Location **A249 MAIDSTONE RD, DANAWAY (MAPPED TO COORDS)**

Description V2 was travelling northeast on Maidstone Rd in lane 2. At point V1 undertook V2 and its front offside hit the rear nearside of V2. V1 and V2 stopped at the scene but D1 refused to give their full details. V2 then left the scene.

Severity SLIGHT Date: 14/03/2019 Thu 18:00 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 602V001A

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	changing lane to right	SW -> NE	2	male
	did not leave c'way	not contacted	offside		?
2 car	not at junction	going ahead other	SW -> NE	1	male
	did not leave c'way	negative	nearside		22

Casualty details Crash resulted in 2 casualties

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
passenger in veh 2	SLIGHT					female 46
passenger in veh 2	SLIGHT					male 6

No.130 Road **A249** Section **177** Map ref: E585748 N162617 Parish: 31
District: Swale

Location **A249 MAIDSTONE RD, DANAWAY (MAPPED TO COORDS)**

Description V1 was travelling southwest on Maidstone Rd towards the rndbt in lane 1. V2 was stationary in a queue towards the rndbt when V1 collided with its rear.

Severity SLIGHT Date: 18/03/2019 Mon 15:45 L Road Surface Wet Speed limit 70mph
Weather Rain

Dual carriageway Not at or within 20m of junction

No Human control within 50m

Contributory Factors: 103V001A 203V001A 308V001B 307V001B 607 V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	not requested	front		50
2 goods < 3.5t	not at junction	waiting to go ahead but held u	NE -> SW	1	male
	did not leave c'way	not requested	back		26

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 1						50

No.131 Road **A249** Section **073** Map ref: E585395 N162001 Parish: 270
District: Maidstone

Location **A249, STOCKBURY RNDT NEAR J/W A249 SITTINGBOURNE RD, STOCKBURY**

Description V1 AND V2 BOTH TRAVELLING FROM SHEERNESS TOWARDS THE STOCKBURY RNDT, V1 WAS IN LANE 1, V2 IN LANE 2, V2 WANTED TO GO STRAIGHT AHEAD, HOWEVER V1 WANTED TO TURN RIGHT, V1 COLLIDED WITH V2, LORRY SIDE SWIPE.

Severity SLIGHT Date: 26/03/2019 Tue 12:53 L Road Surface Dry Speed limit 60mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 403V001A 406V002B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	leaving roundabout	turning right	N -> S	2	male
	did not leave c'way	negative	offside		31
2 car	leaving roundabout	going ahead other	N -> S	1	male
	did not leave c'way	negative	nearside		68

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						68

No.132 Road **A249** Section **176** Map ref: E585474 N162162 Parish: 270
District: Maidstone

Location **A249, MAIDSTONE RD NEAR J/W STOCKBURY RNDT, STOCKBURY**

Description V2 slowed down to a stop in line of traffic with hazard light activated. V1 collided into rear of V2 causing damage. Slight injury to D2, Sect 170 complied, reported due to injury.

Severity SLIGHT Date: 26/03/2019 Tue 05:40 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 car	not at junction	going ahead other	NE -> SW	2	male
	did not leave c'way	not contacted	front		?
2 car	not at junction	stopping	NE -> SW	1	male
	did not leave c'way	not contacted	back		58

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					male
in veh 2						58

No.133 Road **A249** Section **073** Map ref: E585373 N162098 Parish: 270
District: Maidstone

Location **A249, STOCKBURY RNDT J/W M2, STOCKBURY**

Description V2 driving on rndbt, V1 came across and collided with V2. Both parties spoke, details exchanged. Injuries to D2.

Severity SLIGHT Date: 29/03/2019 Fri 08:30 L Road Surface Dry Speed limit 70mph
Weather Fine

Roundabout Roundabout
No Human control within 50m

Contributory Factors: 405V001B

Vehicle details Crash involved 2 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	entering roundabout	going ahead right hand bend	NW -> SE	2	male
	did not leave c'way	not contacted	offside		?
2 car	mid junction	going ahead right hand bend	NW -> SE	1	female
	did not leave c'way	not contacted	nearside		44

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						44

No.134 Road A249 Section 176 Map ref: E585443 N162111 Parish: 270
District: Maidstone

Location A249, MAIDSTONE RD, 34 METRES FROM J/W A249 STOCKBURY RND, STOCKBURY.

Description V2/3/4 have been approaching Stockbury Roundabout coming from Sittingbourne. Speed is a slow crawl due to traffic. V1 has approached stop/start traffic. Not noticed it is now stopped and hit V2. This has then hit V3 which has hit V4. 1 casualty from v2, slight injury. V1 slight damage. V2 probable total loss. V3 medium damage to rear. V4 slight damage to rear light cluster. Dashcam footage taken from V1.

Severity SLIGHT Date: 28/06/2019 Fri 12:06 L Road Surface Dry Speed limit 70mph
Weather Fine

Dual carriageway Not at or within 20m of junction
No Human control within 50m

Contributory Factors: 308V002B 308V003B 405V001B

Vehicle details Crash involved 4 vehicles

vehicle type	location	movement	dir	veh hit	sex
registration		b-test	1st hit	damaged	age
1 goods > 7.5t	not at junction	stopping	NE -> SW	2	female
	did not leave c'way	negative	front		52
2 car	not at junction	waiting to go ahead but held u	NE -> SW	1	female
	did not leave c'way	negative	back		46
3 goods < 3.5t	not at junction	waiting to go ahead but held u	NE -> SW	2	male
	did not leave c'way	negative	back		53
4 car	not at junction	waiting to go ahead but held u	NE -> SW	3	male
	did not leave c'way	negative	back		56

Casualty details Crash resulted in 1 casualty

class	severity	pedestrian location	dir	seat belt	PSV passenger	sex
		pedestrian movement	school name		**to/from school	age
driver/rider	SLIGHT					female
in veh 2						46